Welding Helmet

Category: **Safety & PPE** Type: **Handling note** Priority: **Medium** 3 labs

Covers these lab items: Hand shields; Welding Screen with Head Band

What it is used for

A welding helmet or hand shield protects the face and eyes from welding radiation, sparks, and hot particles.

How to handle

- Inspect the helmet, headband, shield, lens, and filter rating before each use.
- Select the correct filter shade for the welding process and current according to safety guidance.
- Wear the helmet or shield with suitable protective clothing and eye protection as required.
- Position the shield correctly before striking an arc and keep bystanders protected with suitable screens.

Storage

- Store clean and dry in a protective location away from heat, chemicals, and impact.
- Replace damaged lenses, shields, or headbands before further use.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.