
Steady hours
Switching hours
H = 1 h
H = 6 h
H = 24 h
Test RMSE (kW)
0
5
10
15
Pers.
ARIMA
LSTM
TCN
XGB
Mixture