Water Treatment Service Report



Location:

ALAN WOODS BUILDING
TRUSTEES FOR THE WOODS TRUST
JON MULLENS* Technic Client:

Attention: Technician: Date: 14/12/2020 Service Call: 2012-2677 Client No: Contract: N16102 NC11181 Issued By: SYDN Contact No:

HYDRO INDUSTRIES

02 9792 1444

risk Assessment
If risk identified, refer to JSEA for details (√ = pass, X = fail)

☑ Safe access (falls, slips, trips)?
☑ Acceptable noise level with use of PPE?

✓ Safe manual handling? ✓ Adequate lighting?

✓ Shutdown procedure? ✓ Other (refer JSA)

| Results | | | |
|--------------------------------------|-----------------|-------------------------|------|
| | CONDENSER WATER | | R |
| Analysis | | | |
| pН | 7 | 82 | 8.2 |
| M Alkalinity (CaCO3) | 20 | 100 | 300 |
| Chloride (CaCO3) | 200 | 100 | 400 |
| TDS (CaCO3) | 500 | 360 | 1000 |
| Inhibitor | Hydro 2 | | 250 |
| | 200 Hydro 3 | 300 | 350 |
| Total Available Halogen | 0.2 | 1.2 | 1.2 |
| Inhibitor adjustments | | | |
| | Hydro 2 | | |
| Adjustment (L / Kg) | | 0.4 | |
| Adjustment (L / Kg) | Hydro | | |
| | | | |
| Inhibitor pump | Hydro 2 | 60 | |
| Start% / Added / Finish% | 10 | 15 | 100 |
| Operational | | $\overline{\checkmark}$ | |
| Biocide adjustments | | | |
| Adjustment (L / Kg) | Hydro 2 | | |
| , | I harter o | 0.6 | |
| Adjustment (L / Kg) | Hydro 3 | 0 | |
| Biocide pump 1 | | | |
| | Hydro 2 | 56 | |
| Start% / Added / Finish% | 45 | 0 | 45 |
| Operational | | \checkmark | |
| Biocide pump 2 | | | |
| Start% / Added / Finish% | Hydro 3 40 | 60 8.0 | 100 |
| Operational | 40 | 6.0 | 100 |
| Other tests | | i i | |
| Cycles | | 4.3 | |
| ORP set point (mV) | | 420 | |
| | | | |
| Water Meter Reading | | 0 | |
| Make up Reading | | | |
| Bleed Reading | | 0 | |
| Samples | | _ | |
| Heterotrophic Colony Count | | ☑ | |
| Legionella Cooling tower inspection | | $\overline{\mathbf{v}}$ | |
| Visible condition | | Satisfactory. | |
| VISIBLE COLIDITION | | odubidoto.y. | |
| How to interpret the res | ults | | Che |
| All results in mg/L unless | | | |
| indicated otherwise | esired mi | nimum | 7 |
| | | | |
| | | | |

Comments

CTS: Service results indicate all chemical residuals are satisfactory for corrosion and scale control. Cooling tower drains flushed. Removed cleaned and calibrated all dosing system control probes. LOOPS: Both Chilled and Lthot water systems require cleaning and/or redosing with chemical.

Site Signature