

MARKING GUIDELINE

NATIONAL CERTIFICATE MECHANOTECHNOLOGY N3

12 APRIL 2021

This marking guideline consists of 6 pages.

Copyright reserved Please turn over

QUESTION 1: POWER TRANSMISSION, CLUTCHES AND COUPLING OF SHAFTS

1.1 $N(RATIO) = \frac{N(MOTOR)}{N(BELT)}$

$$N(RATIO) = \frac{1250}{650}$$

N(RATIO) = 1,923

$$N(RATIO) = 1,923 : 1 \checkmark$$
 (2)

1.1.2 Type of start vs Duty class vs Operational hours

$$SF = 1.3 \checkmark \checkmark \tag{2}$$

1.1.3 $P(DESIGN) = P(MOTOR) \times SF$

$$P(DESIGN) = 40 \times 1.3 \checkmark$$

$$P = 52 \, kW \, \checkmark \tag{2}$$

1.1.4 D(APPROXIMATE) vs N(MOTOR)

52 kW vs 1 250 r/min

$$D(APPROXIMATE) = 180 \, mm \, \checkmark \checkmark \tag{2}$$

 $1.1.5 P(MOTOR) = \frac{2\pi NT}{60}$

$$T = \frac{40\ 000 \times 60^{\checkmark}}{2\pi \times 1.250^{\checkmark}}$$

$$T = 305,577 \checkmark \frac{1}{2} Nm \checkmark \frac{1}{2}$$
 (3)

- 1.2 1.2.1 Centre distance: the distance from the centre of the driving pulley/sprocket to the centre of the driven pulley/sprocket
 - 1.2.2 Belt deflection: the amount of movement on the belt resulting from its slackness
 - 1.2.3 A machine part that connects a drive shaft with a driven shaft in such a way that the connection can easily be disengaged.
 - 1.2.4 A part of the machine that is used to join one or more shafts to provide single shaft of required length.

 (4×2) (8)

[19]

-3-MECHANOTECHNOLOGY N3

QUESTION 2: BRAKES

2.1 2.1.1 C 2.1.2 D

 (2×1) (2)

- It is easily repairable because of its simplicity.
 - The wheels are coupled separately/independently, hence breaking of a single cable or rod will not affect the entire system.
 - Power failure has no effect on the functionality of this braking system.

 $(Any 2 \times 1)$ (2)

- The system depends on the flow of the electric current.
 - The system depends on electric power.
 - The system will be ineffective due to power failure. (Any 2 × 1) (2) [6]

QUESTION 3: BEARINGS

- 3.1 Part bearings support radial loads in housings
- 3.2 Solid bearings support radial loads in generators, motor starters and idler pulleys
- 3.3 Split bearings support radial loads in reciprocating engines and gear shafts
- 3.4 Thrust bearings support axial/thrust loads in one direction as they are placed on thrust collars
- 3.5 Guide bearings support sliding, and reciprocating movement as found in centre lathes and pump assemblies

 (5×2) [10]

QUESTION 4: WATER PUMPS, COOLING AND LUBRICATION

- 4.1 To minimise chances of explosion
 - To maintain the correct viscosity of the lubricant
 - For the pressure tank to store more air
 - To maintain lubrication of parts

(4)

- 4.2 Liquid − oil
 - Semi-solid grease
 - Solid graphite, boron nitrate

 (3×2) (6)

- 4.3 Open-vane impeller
 - Semi-open or ribbed impeller
 - Enclosed or shrouded impeller (3)

[13]

Copyright reserved Please turn over

QUESTION 5: HYDRAULIC AND PNEUMATIC

5.1 5.1.1

$$A = \frac{\pi a^2}{4}$$

$$d = \sqrt{\frac{0,00163 \times 4}{4}}$$

d = 0.045556 m

 $d = 45.556\sqrt{\frac{1}{2}} \, mm\sqrt{\frac{1}{2}}$

 $5.1.2 p = \frac{F}{A}$


 $F = 420 \times 10^3 \times 0.00163 \checkmark$

 $F = 684.6\sqrt{1/2} N \sqrt{\frac{1}{2}}$


 $(2 \times 2) \qquad (4)$

5.2 When pressure is exerted on the surfaces of a liquid in an enclosed system, the pressure is transmitted with equal force in all directions.

5.3 5.3.1



5.3.2



 $(2 \times 2) \qquad (4)$

[10]

(2)

QUESTION 6: INTERNAL COMBUSTION ENGINES

6.1 A – spark plug

B – combustion chamber

C – piston

D – connecting rod (conrod)

E – displacement volume

(5)

6.2 • Compression stroke

Power stroke

Exhaust stroke

Ì8Ì

8.2.2

-5-MECHANOTECHNOLOGY N3

QUESTION 7: CRANES AND LIFTING MACHINES

Perspex becomes rigid.

7.1 The cost of building, dismantling, and transporting components is very high. The crane has limitations of functionality as it is static on site. The crane's ability to operate is limited to its radius. The covering area of the crane is limited because it is fixed in one position. (4) 7.2 A – trolley/hoisting drum B – rail C – hook (3)[7] **QUESTION 8: MATERIAL AND MATERIAL PROCESSES** 8.1 8.1.1 Overheating causes sagging and collapsing. There is no colour change when heated. Heat tends to soften the metal. (3) 8.1.2 Serious reduction of corrosion-resisting properties due to heat Distortion and grain growth (2)8.2 8.2.1 Nylon becomes stiff.

 (2×1)

Copyright reserved Please turn over

-6-MECHANOTECHNOLOGY N3

QUESTION 9: INDUSTRIAL ORGANISATION AND PLANNING

• To promote good working relations in the workplace.

- To prevent worker grievances/dissatisfaction from accumulating unattended by supervisors
- A means for management to know about the working conditions and relations between employees
- A means of internal dispute resolution
- 9.2 Accurate
 - Objective
 - Clear
 - Brief
 - Insightful
 - Open-minded (Any 5 x 1) (5)
- 9.3 The quantity of the items needed
 - When the items are needed
 - By whom the request is being made (3) [12]

QUESTION 10: ENTREPRENEURSHIP

- 10.1Good organisers
 - Good managers
 - Directors and controllers of activities designed to achieve preestablished goal.
 - Combine the qualities of entrepreneurship with a sound business idea (4)
- 10.2 Competition
 - Expansion potential
 - Business service
 - Nature of the business product
 - Symbiosis
 - Convenience and accessibility
 - The size of the business (Any 4 x 1) (4)

TOTAL: 100

(4)