

T590(E)(J18)T

NATIONAL CERTIFICATE ENGINEERING DRAWING N3

(8090283)

18 July 2018 (X-Paper) 09:00–13:00

REQUIREMENTS: ONE A2 drawing sheet

This question paper consists of 10 pages and 1 answer sheet.

DEPARTMENT OF HIGHER EDUCATION AND TRAINING REPUBLIC OF SOUTH AFRICA

NATIONAL CERTIFICATE ENGINEERING DRAWING N3 TIME: 4 HOURS MARKS: 100

INSTRUCTIONS AND INFORMATION

- 1. Answer ALL the questions.
- Read ALL the questions carefully.
- 3. Number the answers according to the numbering system used in this question paper.
- 4. Use both sides of the DRAWING SHEET.
- 5. Draw a 15 mm border on both sides of the DRAWING SHEET.
- 6. ALL drawing work, including candidate information, must be done in pencil.
- 7. A radius curve stencil may be used to draw smaller arcs.
- 8. Unspecified radii must be R3.
- 9. A balanced layout is very important and candidates will be penalised for poor planning.
- 10. ALL drawing work must conform to the latest SANS 10111 Code of Practice for Engineering Drawing.
- 11. Write neatly and legibly.


MARK ALLOCATION

QUESTION 1: FREEHAND DRAWING			[10]
Correctness			(4)
Line work			(3)
Accuracy and proportion			(3)
			. ,
QUEST	ION 2: SE	CTIONAL DRAWING	[25]
2.1		tness – Full-sectional front view	(6)
2.2		tness – Full-sectional top view	(6)
2.3		tness – Full-sectional right view	(6)
	Line wo	ork – 1 mark per view	(3)
	Accura	cy – 1 mark per view	(3)
Layout and neatness			(1)
QUESTION 3: ASSEMBLY DRAW <mark>ING</mark>			[30]
Correctness			(18)
Line work			(5)
Accuracy			(5)
Layout and neatness			(2)
OHEOT	TON 4. DE	TAILED DRAWING	[00]
		TAILED DRAWING	[20]
4.1		Correctness – Full-sectional front view (Item 1)	(3)
4.2		Correctness – Top view (Item 1)	(5) (4)
4.2	Correctness – Full-sectional front view (Item 2) Line work – 1 mark per view		(3)
		cy – 1 mark per view	(3)
Layout and neatness			(2)
Layout	and neame	555	(2)
QUEST	ION 5: PE	RSPECTIVE DRAWING	[15]
Correctness			
Line work			(8)
Accuracy			
SP + LVP + RVP			
		TOTAL	100

QUESTION 1: FREEHAND DRAWING

FIGURE 1 shows a full-sectional front view of a component.

Make a freehand drawing of the given view approximately full-sized.




QUESTION 2: SECTIONAL DRAWING

FIGURE 2 shows two primary views of a component.

Draw, to scale 1: 1, the following views of the component in first-angle orthographic projection:

- 2.1 A full-sectional front view (9)
- 2.2 A full-sectional top view on cutting plane X-X (8)
- 2.3 A full-sectional left view on cutting plane Y-Y (8)






FIGURE 2 [25]

QUESTION 3: ASSEMBLY DRAWING

FIGURE 3 on the next page shows the primary views of the components of a piston assembly.

The complete list of parts is as follows:

ITEM	DESCRIPTION	QUANTITY
1	Piston	1
2	Connecting rod	1
3	Big end	1
4	Gudgeon pin	1
5	M10 hexagon head bolt	2
6	M10 hexagonal nut	2

Draw, to scale 1: 1, a full-sectional front view of the piston assembly as an assembly drawing.




FIGURE 3 [30]

QUESTION 4: DETAILED DRAWING

FIGURE 4 on the next page shows two primary views of a marking machine.

Draw, to scale 1:1, detailed drawings of the following items in third-angle orthographic projection:

- 4.1 The base (Item 1) showing the following views:
 - 4.1.1 A full-sectional front view (6)
 - 4.1.2 A top view (7)
- 4.2 The frame (Item 2) showing a full-sectional front view (7)

NO hidden detail is necessary.




FIGURE 4 [20]

QUESTION 5: PERSPECTIVE DRAWING

NOTE: This question must be answered on the ANSWER SHEET and attached to the DRAWING SHEET.

Use the information shown on the ANSWER SHEET (attached) to draw a neat two-point perspective view of the machined block.

Point A is situated in line with the centre of vision and up against the picture plane.

Line AB vanishes to the right at 30°.

The distance of the eye in front of the picture plane is 100 mm.

NO hidden detail is necessary.

[15]

TOTAL: 100

(8090283) T590**(E)**(J18)T

ANSWER SHEET QUESTION 5 HORIZON LINE/PICTURE PLANE