# <u>Lab 2</u>

Input			Segment #						
A	В	С	0	1	2	3	4	5	6
0	0	0	1		1	1		1	1
0	0	1				1	1	1	1
0	1	0	1			1	1	1	1
0	1	1	1	1			1	1	1
1	0	0			1		1	1	1
1	0	1	1			1	1	1	1
1	1	0			1		1		1
1	1	1							

\*All blanks mean 0

Segment 0		00	01	11	10
	gineii 0	$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$	1		1	1
1	A		1		

Segment 1		00	01	11	10
		$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$			1	
1	A				

Segment 2		00	01	11	10
	gmem 2	$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$	1			1
1	A	1			


Segment 3		00	01	11	10
		$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$	1	1		1
1	A		1		

Segment 4		00	01	11	10
	eginent 4	$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$		1	1	1
1	A	1	1		1


Segment 5		00	01	11	10
		$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$	1	1	1	1
1	A	1	1		

Segment 6		00	01	11	10
		$\overline{B} \cdot \overline{C}$	$\overline{B} \cdot C$	$B \cdot C$	$B \cdot \overline{C}$
0	$\overline{A}$	1	1	1	1
1	A	1	1		1


### Segment 0




#### Segment 1




### Segment 2




### Segment 3



## Segment 4



## Segment 5



### Segment 6

