

Frequency response of the undamaged frame: three modes, no fourth

