

No admissible exact branch was recovered at the base plate or Floor 1

Base plate

Floor 1

Floor 2

Floor 3

