Autonomous Pool Playing Robot

Hazard Analysis

Ernest Selman selmae@mcmaster.ca 1201291

 $\begin{array}{c} {\rm Guy~Meyer} \\ {\rm meyerg@mcmaster.ca} \\ 1320231 \end{array}$

Eric Le Fort leforte@mcmaster.ca 1308609 Andrew Danha danhaas@mcmaster.ca 1223881

Derek Savery saverydj@mcmaster.ca 1219142

 $\begin{array}{c} {\rm Max~Moore} \\ {\rm moorem8@mcmaster.ca} \\ {\rm 1320009} \end{array}$

January 6, 2017

Contents

1	Ove	erview	2
	1.1	Naming Conventions & Definitions	2
		1.1.1 Definitions	
		1.1.2 Acronyms & Abbreviations	2
2	Haz	zards	3
	2.1	User caught in a Pinch Point	3
	2.2	Harmful Pneumatic Activation	4
	2.3	Jumping Pool Balls	5
	2.4	Dangerous Machine Traversal	
	2.5	Loose Objects Snagged	
\mathbf{L}	ist	of Tables	
	1	Revision History	1
	2	Definitions	
	3	Acronyms and Abbreviations	
\mathbf{L}	ist	of Figures	
	1	System FTA	3
	2	FTA for a user caught in a pinch point	3
	3	FTA for harmful pneumatic activation	4
	4	FTA for jumping pool balls	5
	5	FTA for dangerous machine traversal	
	6	FTA for loose objects being snagged	

Date	Revision #	Comments	Authors
05/01/2017	0	- Initial document creation	Eric Le Fort
06/01/2017	0	- First draft	Eric Le Fort

Table 1: Revision History

1 Overview

This document's purpose is to help illustrate potential hazards associated with the automated pool-playing robot and how those hazards are to be addressed. The Hazards section will describe the section in more detail as well as provide an overall Fault-Tree Analysis (FTA) for this system. Each hazard will have its own subsection which will describe the hazard, discuss mitigation and/or plans of avoidance as well as provide a more detailed view of the portion of the FTA it concerns.

Certain sections may refer to the supporting documents: *High-Level Hardware Design* and *High-Level Software Design* for this project.

1.1 Naming Conventions & Definitions

This section outlines the various definitions, acronyms and abbreviations that will be used throughout this document in order to familiarize the reader prior to reading.

1.1.1 Definitions

Table 2 lists the definitions used in this document. The definitions given below are specific to this document and may not be identical to definitions of these terms in common use. The purpose of this section is to assist the user in understanding the requirements for the system.

Table 2: Definitions

1.1.2 Acronyms & Abbreviations

Table 3 lists the acronyms and abbreviations used in this document.

Table 3: Acronyms and Abbreviations

Acronym/Abbreviation	Meaning
VR	Visual Recognition
μC	Micro-Controller
FTA	Fault-Tree Analysis

2 Hazards

This section will outline all identified hazards associated with this system. Each hazard will be described, plans for avoiding and/or mitigating the effects of that risk will be stated, and a more-detailed FTA for that hazard will be provided.

The following diagram is the FTA for the system with the hazard specific details abstracted out.




Figure 1: System FTA

2.1 User caught in a Pinch Point

Description

When parts in a machine move in close proximity to one another, there is always a risk of harmful pinching. In this project, there are two locations where this may pose a notable risk: where the x-rails meet the arm base and where the y-rail meets the end-effector base.

Plans for Avoidance/Mitigation

All pinch points will be clearly marked in order to signify the danger they present. Furthermore, emergency stop buttons will be located within reach of all pinch points in the case that a user finds themselves being harmed. This allows the damage to be minimized as much as possible in the case of a pinch. Also, a warning will be printed in a visible location on the system in order to warn users of this risk.




Figure 2: FTA for a user caught in a pinch point.

2.2 Harmful Pneumatic Activation

Description

The pneumatic actuator will involve a very fast-moving component in order to strike the cue ball with sufficient force. If there is something in the way of the end-effector other than the cue ball such as the table, other parts of the machine, or a person, there is likely to be resulting damage.

Plans for Avoidance/Mitigation

When the machine is about to take a shot a warning message or sound can be audibly played by the controller in order to alert the user to the upcoming movement. The machine will pause after this sound to allow the user time to stop the machine if there is an issue.




Figure 3: FTA for harmful pneumatic activation.

2.3 Jumping Pool Balls

Description

Pool balls have a tendency to jump off the table if struck in a certain way. If the ball bounces off of the table, there is potential for damage to the machine, the surrounding environment, or a person.

Plans for Avoidance/Mitigation

The end-effector will be designed in such a way that even when striking at its maximum force, the pool balls will never lose contact with the table. However, the user will still be playing on the table and might jump the balls. There is not much able to be done in terms of protecting other people or the surrounding environment unfortunately but the machine itself will be made in such a way that it is durable in areas where a jumping ball will be likely to hit it.




Figure 4: FTA for jumping pool balls.

2.4 Dangerous Machine Traversal

Description

While the machine is traversing, anything in the way may be at risk. For example, depending on the speed, there could be damage due to impact. Another less severe example could involve knocking off items on the edges of the table.

Plans for Avoidance/Mitigation

In order to avoid high speed impacts, the controller will simply not permit motion faster than a certain, safe speed. In terms of the knocking of items off the table, a warning will be printed in a visible location on the system in order to warn users of that risk. In addition, a warning message or sound can be audibly played by the controller in order to alert the user to upcoming movement. The machine will pause after this sound to allow the user time to stop the machine if there is an issue.




Figure 5: FTA for dangerous machine traversal.

2.5 Loose Objects Snagged

Description

At various locations – namely the pinch points listed earlier as well as the rotational motor on the end-effector base and the belts on the x- and y-rails – loose clothing, jewellery or long hair may be caught and pulled in. If these objects are attached to a person, this can lead to strangulation or being pulled into dangerous areas of the machine.

Plans for Avoidance/Mitigation

For this hazard, there in not much to be done in terms of design to prevent the machine from snagging loose objects. However, a warning will be printed in a visible location on the system in order to warn users of this risk.




Figure 6: FTA for loose objects being snagged.