

Figure 8.4-1 Psychrometric chart—SI units. Reference states: H_2O (L, 0°C, 1 atm), dry air (0°C, 1 atm). (Reprinted with permission of Carrier Corporation.)