



H2A SECOM Motor driver

rev1.00 20130414 (C)JDB/HvA





Speed sensor I/O [5/7]

H2A SECOM Motor driver

rev1.00 20130414 (C)JDB/HvA

