

Form No: G118 Version: V1.01 Issued By: SQM Issue Date: Oct' 11 Approved by: MD

NON CONFORMANCE REPORT (NCR)

NCR Number: MTF/2017/G118-004

Location: MT MTM FAIRFIELD Area Audited CARGO/BALLAST TANKS AND

OTHER SPACES

Identified through inspections or audits:

External PSC

Non - Conformance Description

Several grounding cables missing or wasted on cargo tank venting heads.

Name of person making the NCR: Lwin Oo NCR Date: 12-May-2017

Rank or Position: Master

Name of responsible person receiving the NCR Repor

Lwin Oo

Rank or Position: Master

Name of Master or General Manager (MTMSM)

Lwin Oo

Target date for completion: 13-May-2017

Immediate Corrective Action/s

Immediately fixing the missing bounding wires on cargo vent heads.

Verified By: Lwin Oo Immediate Corrective Action completed on 12-May-2017

Rank or Position: Master

Root Cause/s

Inadequate Maintenance, Lack of Motivation

Other:

Preventive Action/s:

Discussed with deck crew. officers and instructed if some thing missing or incorrect regarding safety items must to report immediately and take a correct action.

Office Comment:

All Cargo relate joint need to be provide bond wire. Ship staff Immediately fitted the bond wire at Cargo tank Vents.

Verified By: Capt.AKM Position: Marine Superintendent Verified Date: 14-May-2017

Preventive Action/s Completed & NCR Closed out:

Closure Remarks:

Immediately fitted the bond wire at Cargo tank Vents.

Closed By: Capt.AKM

Closure Date: 18-May-2017