RFQ Details

LIG/2014/DD01-Q01

CONTENTS

AA	GENERAL SERVICES
ВВ	HULL CLEANING, BLASTING AND PAINTING
cc	PRICES FOR TASK OF CARGO TANKS
DD	PRICES FOR TASK OF HULL INTERNAL PLATING
EE	PRICES FOR TASK OF BALLAST TANKS
FF	SHIP SIDE SEA WATER VALVES, SEA CHEST AND HULL ANODES
GG	PROPELLER AND TAILSHAFT
нн	RUDDER AND PINTLES, STEERING GEAR
II	ANCHOR, CABLES, WINDLASS AND MOORING EQUIPMENT WINCH
IJ	DECK PIPING
KK	DECK FITTINGS, ACCESSES, BOLLARDS, HANDRAILS, TANK VENTS
LL	CARGO SYSTEMS-PUMPS, VALVES, PIPELINES, TANK CLEANING, INERT GAS
мм	CARGO CONTROL SYSTEM
NN	ACCOMMODATION
00	BRIDGE AND NAVIGATING EQUIPMENT
PP	BRIDGE RADIO AND COMMUNICATION EQUIPMENT
QQ	INSTRUMENTATION AND CONTROL EQUIPMENT
RR	SAFETY EQUIPMENT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS: U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

23-Mar-2015 Page 3 of 128

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

Short Description:

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description:

assdf afsd afsd

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

23-Mar-2015 Page 4 of 128

New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Cod	е	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-E	EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks :

Short Description:

SSSSSSSSSS

23-Mar-2015 Page 5 of 128

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

Long Description:

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

Long Description : DRRRRRRRRRRR

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description :

REPAIRS

BB-001 Schedule prices for Grit-Blasting

23-Mar-2015 Page 6 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks :

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

23-Mar-2015 Page 7 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

23-Mar-2015 Page 8 of 128

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

Short Description:

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

BB HULL CLEANING, BLASTING AND PAINTING

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 9 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 10 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 11 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 12 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 13 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 14 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 15 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

CC PRICES FOR TASK OF CARGO TANKS

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 16 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 17 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 18 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 19 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 20 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 21 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 22 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

DD PRICES FOR TASK OF HULL INTERNAL PLATING

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 23 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 24 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

11011 000000 11 00 201

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 25 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks :

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description :

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 26 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 27 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 28 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description :**

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 29 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

EE PRICES FOR TASK OF BALLAST TANKS

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 30 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 31 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 32 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 33 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

Long Description :

DRRRRRRRRRRRRRRRR

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 34 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 35 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description :**

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 36 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

FF SHIP SIDE SEA WATER VALVES, SEA CHEST AND HULL ANODES

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 37 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 38 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 39 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 40 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 41 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 42 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 43 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

GG PROPELLER AND TAILSHAFT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 44 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 45 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 46 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 47 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 48 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 49 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 50 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

HH RUDDER AND PINTLES, STEERING GEAR

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 51 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 52 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 53 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description :

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 54 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 55 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 56 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 57 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

I ANCHOR, CABLES, WINDLASS AND MOORING EQUIPMENT WINCH

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 58 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 59 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 60 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 61 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 62 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 63 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 64 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

JJ DECK PIPING

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 65 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 66 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 67 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 68 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 69 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 70 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 71 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

KK DECK FITTINGS, ACCESSES, BOLLARDS, HANDRAILS, TANK VENTS

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 72 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdad adasdasdsadasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 73 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 74 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 75 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 76 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 77 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 78 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

LL CARGO SYSTEMS-PUMPS, VALVES, PIPELINES, TANK CLEANING, INERT GAS

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 79 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 80 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description :

New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA	- 150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 81 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description :

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 82 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 83 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 84 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 85 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

MM CARGO CONTROL SYSTEM

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 86 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 87 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 88 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description :

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 89 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 90 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 91 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 92 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

NN ACCOMMODATION

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 93 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 94 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description :

New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 95 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description :

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 96 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 97 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 98 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 99 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

OO BRIDGE AND NAVIGATING EQUIPMENT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 100 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 101 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 102 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 103 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 104 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 105 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 106 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

PP BRIDGE RADIO AND COMMUNICATION EQUIPMENT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 107 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 108 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 109 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks:

Short Description:

GFGFFRF

23-Mar-2015 Page 110 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 111 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 112 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 113 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

QQ INSTRUMENTATION AND CONTROL EQUIPMENT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 114 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdasdasdasdasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 115 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description : assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 116 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 117 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 118 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 119 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 120 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

RR SAFETY EQUIPMENT

AA-001 Docking / undocking

adaasdasddsadasds

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-01	0.00	DAYS : U	10.00	100.00	0.00	1000.00	Yard Cost	Yes

Vendor Remarks:

d

Short Description:

23-Mar-2015 Page 121 of 128

UPDATED: Docking / undocking incl. tugs, mooring, and pilot as well as first 2 days in dock, dock rent Dry-dock the vessel as required for a thorough examination, cleaning, painting and all specified repairs to the underwater body.

Upon the satisfactory completion of all work and with the approval of the Owner's Repair Inspector, undock the vessel. Prior to dock, the disposition of all fuel, fresh water and ballast water to be checked and recorded with the Captain and the docking trim to be agreed upon. Similar precautions are to be taken prior to flooding dock on completion. The vessel to be docked and undocked without assistance of vessel's main engine and properly shore lash in dry-dock. Keel blocks with soft wood caps to be spaced not less than one (1) meter between centers, except in way of forward and after ends of ship, and with a minimum headroom of one and a half (1.5) meters, in order to properly clean and apply paint to the hull between blocks.

Special shores are to be placed under all tanks containing fuel oil, fresh water or ballast water if found necessary. Vessel is to remain in dock sufficient time to permit all paint to dry, as directed by Owner's Representative.

The vessel will require a total of _____ running days in dry-dock for the completion of all underwater work as specified in this repair specification.

Yard to submit a drawing showing how the blocks were arranged in dock in relation to ships flat bottom and frames for owner's reference to next dry-docking and bottom painting.

Sizes of blocks and spacing to be mentioned on the drawing.

For first (haul-in) days

For each additional lay day

Estimated days X cost each day

Long Description:

UPDATED: asdasdasdasdasdasdad adasdasdsadasd

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-02							Non Yard Cost	No

Vendor Remarks:

Short Description:

NOTE: The necessary services of tugboats, line handlers, etc., for shifting the vessel to carry out this item are covered under a separate item. Any additional services or facilities, not specifically mentioned in this specification which may be required by the Contractor or the local Port Authorities for the safe and expedient fulfillment of this item are to be clearly specified and a price or prices for the same indicated.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-03								

Vendor Remarks:

Short Description:

New added job45456 Edited

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-04								

Vendor Remarks:

23-Mar-2015 Page 122 of 128

ddddd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-05								

Vendor Remarks:

Short Description:

fsafd fsdfs

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-06								

Vendor Remarks:

Short Description: assdf afsd afsd

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-07								

Vendor Remarks:

Short Description:

eeeeeeeeeeeee werwer rwer

Long Description :

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-08								

Vendor Remarks:

Short Description: New SubJob 11-09-2014

11011 000000 11 00 201

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	150.00	Days					Yard Cost	No

Vendor Remarks:

23-Mar-2015 Page 123 of 128

Created New Job 19-09-2014

Long Description:

Created New Job 19-09-2014Created New Job 19

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	20.00	Years					Yard Cost	No

Vendor Remarks:

Short Description:

New

Long Description:

New

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	50.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECT DETAILS DEFECT DETAILS DEFECT DETAILS

Long Description:

REPAIRS CARRIED OUT REPAIRS CARRIED OUT REPAIRS CARRIED OUT

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA-	7.00	7					Yard Cost	No

Vendor Remarks:

Short Description:

SSSSSSSSSS

Long Description:

ASDF

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-001-EXTRA	- 8.00	8					Yard Cost	No

Vendor Remarks :

Short Description:

GFGFFRF

23-Mar-2015 Page 124 of 128

FFFF

AA-003 Wharfage

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA-	10.00	MONTHS					Yard Cost	Yes

Vendor Remarks:

Short Description:

new job

Long Description:

new job

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-003-EXTRA	9.00	111111					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

DDDDDDDDD

AA-004 Gangway (s)

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
AA-004-EXTRA-	1250.00	Days					Yard Cost	No

Vendor Remarks:

Short Description:

DEFECTS

Long Description:

REPAIRS

BB-001 Schedule prices for Grit-Blasting

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-01		zc xzczczxo						

Vendor Remarks:

Short Description:

Quote separate prices per square meter for the following grit blasting, including staging when necessary:-

Long Description:

23-Mar-2015 Page 125 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-02								

Vendor Remarks:

Short Description:

TOPSIDE scattered areas per square meter

- (a) Grit sweeping
- (b) Grit blasting to Sa 2.0
- (c) Grit blasting to Sa 2.5
- (d) Paint coating touch-up primer and top coat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-03								

Vendor Remarks:

Short Description:

TOPSIDE whole area per square meter

- (e) Grit sweeping
- (f) Grit blasting to Sa 2.0
- (g) Grit blasting to Sa 2.5
- (h) Paint coating full coat primer and topcoat.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-04								

Vendor Remarks:

Short Description:

VERTICAL SIDES area per square meter

- (i) Grit sweeping
- (j) Grit blasting to Sa 2.0
- (k) Grit blasting to Sa 2.5
- (I) Paint coating touch up primer and spc.
- (m) Paint coating full coat primer and spc.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-05								

Vendor Remarks:

Short Description:

FLATBOTTOM area per square meter

- (n) Grit sweeping
- (o) Grit blasting to Sa 2.0
- (p) Grit blasting to Sa 2.5
- (q) Paint coating touch-up primer and spc
- (r) Paint coating full coat primer and spc.

23-Mar-2015 Page 126 of 128

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-06								

Vendor Remarks:

Short Description:

During the pre-treatment and paint application, the steel temperature, air temperature and humidity to be measured four (4) times daily and reported in diagram form to the Owner's Representative.

Standard shipyard best practices are to be followed to maintain hull painting preparation, application and quality **Long Description**:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-07								

Vendor Remarks:

Short Description:

Silicon paint to be applied: Quote for 3/5 yearly paint: vertical & flat bottom requires complete blasting to Sa 2.5 standard and will be apply two coat of primer, one tie coat and final Silicon paint and also provided details separately.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-08		qweqweqwe						

Vendor Remarks:

Short Description:

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-001-EXTRA-	100.00	Month					Non Yard Cost	Yes

Vendor Remarks:

Short Description:

asdf

Long Description:

asdf

BB-008 Additional costs for Silicon application

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-01								

Vendor Remarks:

23-Mar-2015 Page 127 of 128

Tools and equipment such as hoses.

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-02								

Vendor Remarks:

Short Description:

B. Masking of top sides

Long Description:

Job Code	Bid Qty	Unit	Quote Qty.	Unit Price	Disc(%)	Net Amount	Cost Category	Outside Repair
BB-008-03								

Vendor Remarks:

Short Description:

Please indicate any extra days in docking for this paint coating application.

Please note International paints requirements and procedures for Silicon application.

Please also indicate any other additional charges that are included for application of the Intersleek hull paint **Long Description**:

23-Mar-2015 Page 128 of 128