

- (1) the location replaces the orientation if a dimension is possible between current feature and primary or secondary feature
- (2) the datum reference frame must be defined with comment
- (3) symbol (M) must be added on toleranced surface and on datum surface if this surface is a feature of size with clearance.