

Chopsticks squeezed into rubber ractangle

Chopsticks
- similar to IRL
- sensors to detect pressure

Controller with movement and two selection buttons for menus

Handle / Controller?
- Rubber
- Allow for chopstick movement
- Sensor to detect pressure
- Houses buttons for selection
- acts as a handle (sort of)

Parts List				
Item	Qty	Part Number	Description	Material
4	1	Component1		ABS Plastic
5	1	Component2		ABS Plastic





Dept.	Technical reference	Created by: Kristian Menes 2022-04-22	Approved by:
		Document type:	Document status:
		Title: **Hardware Final Chopsticks**	DWG No.:
			Rev. / Date of issue / Sheet: 1/1

Parts List				
Item	Qty	Part Number	Description	Material
6	1	Component3		Rubber, Silicone









Dept	Technical reference	Created by	Approved by
		Kristian Menes 2022-04-22	
		Document type	Document status
		Title: Hardware Final Chopsticks	DWG No.
			Rev. / Date of issue / Sheet: 1/1









Dept.	Technical reference	Created by: Kristian Menes 2022-04-22	Approved by
		Document type	Document status
		Title: **Hardware Final Chopsticks**	DWG No.
			Rev. / Date of issue / Sheet: 1/1

Parts List				
Item	Qty	Part Number	Description	Material
1	1	Component6		ABS Plastic
2	1	Component5		ABS Plastic
3	1	Component10		ABS Plastic
4	1	Component9		ABS Plastic
5	1	Component11		ABS Plastic
6	1	Component4		Rubber, Silicone
7	1	Component3		Rubber, Silicone
8	1	Component2		ABS Plastic
9	1	Component1		ABS Plastic
10	1	ADXL345 Digital Accelerometer		
11	1	ArduinoMicro		Steel
12	1	Component8		ABS Plastic
13	1	Component7		ABS Plastic
14	6	Button_red		Steel









Dept.	Technical reference	Created by Kristian Menes 2022-04-22	Approved by
		Document type	Document status
		Title Hardware Final Chopsticks	DWG No.
			Rev. / Date of issue / Sheet 1/1


a b c d e
f g h i j
1 2 3 4 5 7 8 9 10 11 13 14 15 16 17 19 20 21 22 23 25 26 27 28 29 30
9V

Code
Start Simulation
Send To
9V


Printer
1.750
Filament diameter
0.400
Nozzle diameter
1
Number of extruders
200.000
Bed X size
200.000
Bed Y size
Bed center is (0,0)
Control
0
Start at GCode line
Step (mm)
Reset
Clear below
Pause
Auto pause
Show trajectory
Show overlaps and overhangs (?)
Automatic deposition height & width (?
Status
38633
GCode line
0.400
235.00
10.000
XYZ (mm)
Flow (mm^3/sec)
Speed (mm/sec)
dangling (red)
overlaps (blue)
;FLAVOR:Marlin
;TIME:6872
;Filament used: 4.74985m
;Layer height: 0.2
;MINX:93.587
;MINY:24.4
;MINZ:0.2
;MAXX:141.306
;MAXY:162.099
;MAXZ:12
;Generated with Cura_SteamEngine 4.13.1
M140 S50
M105
M190 S50
M104 S200
M105
M109 S200
M82 ;absolute extrusion mode
; Ender 3 Custom Start G-code
G92 E0 ; Reset Extruder
G28 ; Home all axes
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X0.1 Y20 Z0.3 F5000.0 ; Move to start positior
G1 X0.1 Y200.0 Z0.3 F1500.0 E15 ; Draw the first
G1 X0.4 Y200.0 Z0.3 F5000.0 ; Move to side a litt
G1 X0.4 Y20 Z0.3 F1500.0 E30 ; Draw the second li
G92 E0 ; Reset Extruder
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X5 Y20 Z0.3 F5000.0 ; Move over to prevent blc
G92 E0
G92 E0
G1 F2700 E-5
;LAYER_COUNT:61
;LAYER:0
M107
G0 F6000 X94.287 Y31.573 Z0.2




```
;FLAVOR:Marlin
;TIME:4051
;Filament used: 2.94186m
;Layer height: 0.2
;MINX:82.3
;MINY:67.175
;MINZ:0.2
;MAXX:152.7
;MAXY:167.825
;MAXZ:3.6
;Generated with Cura_SteamEngine 4.13.1
M140 S50
M105
M190 S50
M104 S200
M105
M109 S200
M82 ;absolute extrusion mode
; Ender 3 Custom Start G-code
G92 E0 ; Reset Extruder
G28 ; Home all axes
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X0.1 Y20 Z0.3 F5000.0 ; Move to start positior
G1 X0.1 Y200.0 Z0.3 F1500.0 E15 ; Draw the first
G1 X0.4 Y200.0 Z0.3 F5000.0 ; Move to side a litt
G1 X0.4 Y20 Z0.3 F1500.0 E30 ; Draw the second li
G92 E0 ; Reset Extruder
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X5 Y20 Z0.3 F5000.0 ; Move over to prevent blc
G92 E0
G92 E0
G1 F2700 E-5
;LAYER_COUNT:18
;LAYER:0
M107
G0 F6000 X85.516 Y72.306 Z0.2
```




```
;FLAVOR:Marlin
;TIME:9520
;Filament used: 6.54343m
;Layer height: 0.2
;MINX:84.565
;MINY:69.44
;MINZ:0.2
;MAXX:150.435
;MAXY:165.56
;MAXZ:20.6
;Generated with Cura_SteamEngine 4.13.1
M140 S50
M105
M190 S50
M104 S200
M105
M109 S200
M82 ;absolute extrusion mode
; Ender 3 Custom Start G-code
G92 E0 ; Reset Extruder
G28 ; Home all axes
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X0.1 Y20 Z0.3 F5000.0 ; Move to start positior
G1 X0.1 Y200.0 Z0.3 F1500.0 E15 ; Draw the first
G1 X0.4 Y200.0 Z0.3 F5000.0 ; Move to side a litt
G1 X0.4 Y20 Z0.3 F1500.0 E30 ; Draw the second li
G92 E0 ; Reset Extruder
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X5 Y20 Z0.3 F5000.0 ; Move over to prevent blc
G92 E0
G92 E0
G1 F2700 E-5
;LAYER_COUNT:103
;LAYER:0
M107
G0 F6000 X87.189 Y73.914 Z0.2
```




```
;FLAVOR:Marlin
;TIME:841
;Filament used: 0.505516m
;Layer height: 0.2
;MINX:93.516
;MINY:87.769
;MINZ:0.2
;MAXX:141.477
;MAXY:147.226
;MAXZ:4
;Generated with Cura_SteamEngine 4.13.1
M140 S50
M105
M190 S50
M104 S200
M105
M109 S200
M82 ;absolute extrusion mode
; Ender 3 Custom Start G-code
G92 E0 ; Reset Extruder
G28 ; Home all axes
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X0.1 Y20 Z0.3 F5000.0 ; Move to start positior
G1 X0.1 Y200.0 Z0.3 F1500.0 E15 ; Draw the first
G1 X0.4 Y200.0 Z0.3 F5000.0 ; Move to side a litt
G1 X0.4 Y20 Z0.3 F1500.0 E30 ; Draw the second li
G92 E0 ; Reset Extruder
G1 Z2.0 F3000 ; Move Z Axis up little to prevent
G1 X5 Y20 Z0.3 F5000.0 ; Move over to prevent blc
G92 E0
G92 E0
G1 F2700 E-5
;LAYER_COUNT:20
;LAYER:0
M107
G0 F6000 X97.991 Y92.662 Z0.2
```