

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION			
DISTRICT ADDRESS AND PHONE NUMBER 555 Winderley Place, Suite 200 Maitland, FL 32751 (407) 475-4700 Fax: (407) 475-4768		DATE(S) OF INSPECTION 10/14/2025-10/16/2025 FEI NUMBER 3014650073	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED Dominic Verne Sharma, Chief Executive Officer			
FIRM NAME Silq Technologies Corporation		STREET ADDRESS 323 Sunny Isles Blvd Fl 7	
CITY, STATE, ZIP CODE, COUNTRY Sunny Isles Beach, FL 33160-4232		TYPE ESTABLISHMENT INSPECTED Manufacturer	
This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observations, and do not represent a final Agency determination regarding your compliance. If you have an objection regarding an observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.			
<i>The observations noted in this Form FDA-483 are not an exhaustive listing of objectionable conditions. Under the law, your firm is responsible for conducting internal self-audits to identify and correct any and all violations of the quality system requirements.</i>			
DURING AN INSPECTION OF YOUR FIRM I OBSERVED: OBSERVATION 1 An MDR report was not submitted within 30 days of receiving or otherwise becoming aware of information that reasonably suggests that a marketed device has malfunctioned and would be likely to cause or contribute to a death or serious injury if the malfunction were to recur. Specifically, Your firm failed to submit a Medical Device Report (MDR) within the required 30-day timeframe after becoming aware of a device malfunction involving your Urological Catheter, a Class II medical device. This malfunction necessitated medical intervention for the patient. According to your internal procedure "Medical Device Reporting" (QM.SLQ022, Revision A, Effective Date: September 25, 2020), Section 6.5 MDR Reporting Timeframes specifies that reports are "due within 30 calendar days of becoming aware of information that reasonably suggests that the device may have caused or contributed to a death, serious injury, or reportable malfunction." Since January 2023, your firm has received at least two (2) complaints documenting device malfunctions that required patients to seek medical intervention, yet the corresponding MDR submissions were not filed within the regulatory timeframe.			
OBSERVATION 2 Procedures for design change have not been adequately established.			
SEE REVERSE OF THIS PAGE	EMPLOYEE(S) SIGNATURE Marvin A Marenco, Investigator _____ X		DATE ISSUED 10/16/2025
FORM FDA 483 (09/08) PREVIOUS EDITION OBSOLETE INSPECTIONAL OBSERVATIONS PAGE 1 of 3 PAGES			

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION			
DISTRICT ADDRESS AND PHONE NUMBER 555 Winderley Place, Suite 200 Maitland, FL 32751 (407) 475-4700 Fax: (407) 475-4768		DATE(S) OF INSPECTION 10/14/2025-10/16/2025 FEI NUMBER 3014650073	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED Dominic Verne Sharma, Chief Executive Officer			
FIRM NAME Silq Technologies Corporation		STREET ADDRESS 323 Sunny Isles Blvd Fl 7	
CITY, STATE, ZIP CODE, COUNTRY Sunny Isles Beach, FL 33160-4232		TYPE ESTABLISHMENT INSPECTED Manufacturer	
Specifically, Since November 2024, your firm has distributed approximately 280 urological catheters (Class II medical devices for urinary tract drainage) without obtaining proper approval for a design change. This distribution occurred following an unauthorized design change implemented by your contract manufacturer. On November 6, 2024, your contract manufacturer informed your firm via written correspondence received from their contract manufacturer that they "implemented an improved valve that ensures secure placement and prevents dislodgement." Despite receiving this notification, your firm proceeded to distribute the modified devices without completing the required regulatory processes. Per your internal procedure "Design Control Program" (QM.SLQ004, Revision A, effective September 25, 2020), your firm failed to approve a design change prior to its implementation and distribution.			
SEE REVERSE OF THIS PAGE	EMPLOYEE(S) SIGNATURE Marvin A Marenco, Investigator		DATE ISSUED 10/16/2025
	X _____		
FORM FDA 483 (09/08) PREVIOUS EDITION OBSOLETE INSPECTIONAL OBSERVATIONS PAGE 2 of 3 PAGES			

[illegible]

PAGE 3 of 3 PAGES

The observations of objectionable conditions and practices listed on the front of this form are reported:

1. Pursuant to Section 704(b) of the Federal Food, Drug and Cosmetic Act, or
2. To assist firms inspected in complying with the Acts and regulations enforced by the Food and Drug Administration.

Section 704(b) of the Federal Food, Drug, and Cosmetic Act (21 USC 374(b)) provides:

"Upon completion of any such inspection of a factory, warehouse, consulting laboratory, or other establishment, and prior to leaving the premises, the officer or employee making the inspection shall give to the owner, operator, or agent in charge a report in writing setting forth any conditions or practices observed by him which, in his judgment, indicate that any food, drug, device, or cosmetic in such establishment (1) consists in whole or in part of any filthy, putrid, or decomposed substance, or (2) has been prepared, packed, or held under insanitary conditions whereby it may have become contaminated with filth, or whereby it may have been rendered injurious to health. A copy of such report shall be sent promptly to the Secretary."