



October 31st, 2025

U.S. Food and Drug Administration
Office of Medical Device and Radiological Health Inspectorate Division 2 – South
ATTN: OMDRHI Program Division Director
555 Winderley Place, Suite 200
Maitland, FL 32751
(407) 475-4700
E-mail: OII-Devices-South-Firm-Response@fda.hhs.gov

Re: FDA-483 Dated 10/16/25 Response for SILQ Technologies Corp. (FEI Number 3014650073)

To Whom It May Concern:

On 10/16/2025, Silq Technologies Corporation received a 483 from FDA Investigator Marvin Marenco for an audit performed from 10/14/2025 to 10/16/2025. This memo outlines the decisive actions taken by Silq to resolve the two issues identified in the aforementioned 483:

FDA Observation #1: An MDR report was not submitted within 30 days of receiving or otherwise becoming aware of information that reasonably suggests that a marketed device has malfunctioned and would be likely to cause or contribute to a death or serious injury if the malfunction were to recur.

Silq Deficiency: Specifically, your firm failed to submit a Medical Device Report (MDR) within the required 30-day timeframe after becoming aware of a device malfunction involving your Urological Catheter, a Class II medical device. This malfunction necessitated medical intervention for the patient. According to your internal procedure "Medical Device Reporting" (QM.SLQ022, Revision A, Effective Date: September 25, 2020), Section 6.5 MDR Reporting Timeframes specifies that reports are "due within 30 calendar days of becoming aware of information that reasonably suggests that the device may have caused or contributed to a death, serious injury, or reportable malfunction." Since January 2023, your firm has received at least two (2) complaints documenting device malfunctions that required patients to seek medical intervention, yet the corresponding MDR submissions were not filed within the regulatory timeframe.

Silq Resolution: Specific actions include:

CONFIDENTIAL



- CAPA 002-2025 was initiated on October 20, 2025 to address this deficiency.
- MDRs shall be submitted for both of the specific complaints cited in the 483.
- All other complaints received since the previous FDA inspection (January 2023) have been reviewed in detail to determine if there are any additional instances which should have triggered an MDR. No such instances were found.
- Silq's Product Complaint Form (FM1-QM.SLQ021) shall be revised. In addition to the existing complaint reportability determination questions regarding a device related event's potential to contribute to a death or permanent damage to bodily functions/structures, a new line item will be included to specifically identify any instances which entailed medical or surgical intervention related to our product outside of the patient's normal standard of care.
- Therefore, in the future, any event related to our product which entails medical or surgical intervention outside of the patient's normal standard of care will result in a determination that the event will be reported via an MDR.
- Target timeline to close CAPA 002-2025 is November 28, 2025.

FDA Observation #2: Procedures for design change have not been adequately established.

Silq Deficiency: Specifically, since November 2024, your firm has distributed approximately 280 urological catheters (Class II medical devices for urinary tract drainage) without obtaining proper approval for a design change. This distribution occurred following an unauthorized design change implemented by your contract manufacturer. On November 6, 2024, your contract manufacturer informed your firm via written correspondence received from their contract manufacturer that they "implemented an improved valve that ensures secure placement and prevents dislodgement." Despite receiving this notification, your firm proceeded to distribute the modified devices without completing the required regulatory processes. Per your internal procedure "Design Control Program" (QM.SLQ004, Revision A, effective September 25, 2020), your firm failed to approve a design change prior to its implementation and distribution.

Silq Resolution: Specific actions include:



- CAPA 003-2025 was initiated on October 20, 2025 to address this deficiency.
- A formal regulatory assessment associated with this design change (i.e., dimensional change to a minor, non-patient contacting component)
- has been performed. Based on this assessment, it has been determined that the change does not require a new 510(k) submission.
- An internal Letter-to-File is in the process of being generated to document the rationale for this regulatory determination. This Letter-to-File will include a step-by-step assessment against the requirements of the FDA guidance “Deciding When to Submit a 510(k) for a Change to an Existing Device”, and reference our internal procedure “Design Control Program” (QM.SLQ004, Revision A. effective September 25, 2020).
- Target timeline to close CAPA 003-2025 is November 28, 2025.

In summary, the Company is in the process of decisively correcting these issues and taking preventive measures to ensure that they do not recur. The two CAPAs which have been initiated will both be closed by November 28, 2025.

Best Regards,

D. Verne Sharma
CEO
Silq Technologies Corporation