

	DOCUMENT TITLE: Internal Quality Audit Final Report	Revision: A
	DOCUMENT #: FM3-QM.SLQ017	Effective Date: 25Sep2020

Internal Quality Audit Final Report

AREA OR SECTION OF QUALITY SYSTEM AUDITED:	Current Good Manufacturing Practices 21 CFR Part 820; ISO 13485:2016 Sections 5.6, 6, 7, and 8
AUDIT NUMBER:	23-02
DATE(S) OF AUDIT:	November 28 – 29, 2023
DATE OF REPORT:	28 Dec 2023
PURPOSE OF AUDIT:	GMP/QSIT audit
AUDITOR(S):	Bryan Wong
APPLICABLE STANDARDS:	21 CFR 820, ISO 13485:2016
FINDINGS: (REFERENCE APPROPRIATE CAPA NUMBER, IF APPLICABLE)	Four (4) findings were observed during the audit. Finding No.: Finding #1 Audit Criteria: 21 CFR Part 820, ISO 13485:2016 Corrective Action Plan Due Date: 29 Jan 2024 Corrective Action Implementation Due Date: 29 Mar 2024 Document Ref #: Training SOP, QP-017 Rev E Action Required: Submit corrective action plan Finding: Per Section 8.3.4 of Training procedure (QP-017 Rev E), “Retraining shall take place yearly based on previous training date per procedure.” Based on review of employee training records, this requirement has not been fulfilled. Requirement: 21 CFR 820.25 Personnel (b) <i>“Training. Each manufacturer shall establish procedures for identifying training needs and ensure that all personnel are trained to adequately perform their assigned responsibilities. Training shall be documented.”</i> ISO 13485:2016 cl. 6.2 <i>“The organization shall document the process(es) for establishing competence, providing needed training, and ensuring awareness of personnel. The organization shall:</i>



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

- a) *Determine the necessary competence for personnel performing work affecting product quality;*
- b) *Provide training or take other actions to achieve or maintain the necessary competence;*
- c) *Evaluate the effectiveness of the actions taken;*
- d) *Ensure that its personnel are aware of the relevance and importance of their activities and how they contribute to the achievement of the quality objectives;*
- e) *Maintain appropriate records of education, training, skills and experience."*

Objective Evidence:

There was no evidence of annual training (i.e., within the last 12 months) for Sean Tamayo for document #'s QM-01, QP-008, QP-017, QP-019, QP-026, and MLP-SLQ-0001. There was no evidence of annual training for Aaron Rogers for document #'s QM-01, QP-001, QP-008, QP-017, and QP-023. There was no evidence of annual training for Larry Dacoron for document #'s QM-01, QP-001., QP-005, QP-008, QP-009, and QP-023. There is no evidence of annual training for James Romero for QM-01.

Finding No.: Finding #2

Audit Criteria: 21 CFR Part 820, ISO 13485:2016

Corrective Action Plan Due Date: 29 Jan 2024

Corrective Action Implementation Due Date: 29 Mar 2024

Document Ref #: Calibration SOP, QP-020 Rev D

Action Required: Submit corrective action plan

Finding:

The calibration frequency for pin gauge set (ES-0047-01) and temperature gauge (ES-0119-03) do not comply with requirements outlined in QP-020 Table 7.1.5. There is no documentation or impact analysis to justify change in calibration frequency.

Requirement:

21 CFR 820.70 (g)(1) (g)(3)

"Equipment. Each manufacturer shall ensure that all equipment used in the manufacturing process meets specified requirements and is appropriately designed, constructed, placed, and installed to facilitate maintenance, adjustment, cleaning, and use.

(1) Maintenance schedule. Each manufacturer shall establish and maintain schedules for the adjustment, cleaning, and other



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

maintenance of equipment to ensure that manufacturing specifications are met. Maintenance activities, including the date and individual(s) performing the maintenance activities, shall be documented.

(3) Adjustment. Each manufacturer shall ensure that any inherent limitations or allowable tolerances are visibly posted on or near equipment requiring periodic adjustments or are readily available to personnel performing these adjustments."

21 CFR 820.72 (a)

"Control of inspection, measuring, and test equipment. Each manufacturer shall ensure that all inspection, measuring, and test equipment, including mechanical, automated, or electronic inspection and test equipment, is suitable for its intended purposes and is capable of producing valid results. Each manufacturer shall establish and maintain procedures to ensure that equipment is routinely calibrated, inspected, checked, and maintained. The procedures shall include provisions for handling, preservation, and storage of equipment, so that its accuracy and fitness for use are maintained. These activities shall be documented."

ISO 13485:2016 cl. 7.5

"Production and service provision shall be planned, carried out, monitored and controlled to ensure that product conforms to specification. As appropriate, production controls shall include but are not limited to: ...

d) availability and use of monitoring and measuring equipment"

Objective Evidence:

During review of calibration records for pin gauge set (ES-0047-01) and temperature gauge (ES-0119-03), the calibration frequency does not align with requirements in Calibration procedure (OP-020 Rev D Table 7.1.5).

Finding No.: Finding #3

Audit Criteria: 21 CFR Part 820, ISO 13485:2016

Corrective Action Plan Due Date: 29 Jan 2024

Corrective Action Implementation Due Date: 29 Mar 2024

Document Ref #: CERTS Monitoring Report (7/31/23)

Action Required: Submit corrective action plan

Finding:



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

Failed pressurization test for cleanroom to gowning room. Pressure recorded was 0.018. Acceptance criteria is 0.02. (Note: Report references acceptance criteria from QP-018 Rev H, however, the current revision is Rev P.)

Requirement:

21 CFR 820.70 (c), (f)

“(c) Environmental control. Where environmental conditions could reasonably be expected to have an adverse effect on product quality, the manufacturer shall establish and maintain procedures to adequately control these environmental conditions. Environmental control system(s) shall be periodically inspected to verify that the system, including necessary equipment, is adequate and functioning properly. These activities shall be documented and reviewed.

(f) Buildings. Buildings shall be of suitable design and contain sufficient space to perform necessary operations, prevent mixups, and assure orderly handling.

ISO 13485:2016 cl. 6.3, 6.4

“6.3 Infrastructure

The organization shall document the requirements for the infrastructure needed to achieve conformity to product requirements, prevent product mix-up and ensure orderly handling of product. Infrastructure includes, as appropriate:

- a) Buildings, workspace and associated utilities;...*

6.4.1 Work environment

The organization shall document the requirements for the work environment needed to achieve conformity to product requirements. If the conditions for the work environment can have an adverse effect on product quality, the organization shall document the requirements for the work environment and the procedures to monitor and control the work environment.”

Objective Evidence:

CERTS cleanroom and gowning room (Suite 104) monitoring report dated 7/31/23. Cleanroom to gowning room pressurization. No evidence of internal Pathway review of results. No evidence of corrective action with regard to failure in pressurization test.

Finding No.: Finding #4



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

Audit Criteria: 21 CFR Part 820, ISO 13485:2016
Corrective Action Plan Due Date: 29 Jan 2024
Corrective Action Implementation Due Date: 29 Mar 2024
Document Ref #: Receiving inspection record SLQ-5004
Action Required: Submit corrective action plan

Finding:

During review of inspection records for SLQ-5004, the inspection requirements were not fulfilled.

- a) No evidence of a packing slip with acceptance label per Section 7.8.3 of QP-009 Rev E.
- b) No evidence of shipment inspection per Section 7.4 of QP-009 Rev E.

Requirement:

21 CFR 820.50 (a)(2)

"Each manufacturer shall establish and maintain procedures to ensure that all purchased or otherwise received product and services conform to specified requirements.

(a)(2) Define the type and extent of control to be exercised over the product, services, suppliers, contractors, and consultants, based on the evaluation results."

21 CFR 820.80 (a)

"(b) Receiving acceptance activities. Each manufacturer shall establish and maintain procedures for acceptance of incoming product. Incoming product shall be inspected, tested, or otherwise verified as conforming to specified requirements. Acceptance or rejection shall be documented."

ISO 13485:2016 cl. 7.4.3, 8.4

"7.4.3 Verification of purchased product

The organization shall establish and implement the inspection or other activities necessary for ensuring that purchased product meets specified purchasing requirements. The extent of verification activities shall be based on the supplier evaluation results and proportionate to the risks associated with the purchased product."

Objective Evidence:

The receiving inspection record for label stock SLQ-5004 (order placed on 1/24/22) did not include documented evidence of a packing slip or shipment inspection as required per Section



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

RECOMMENDATIONS:

7.8.3 and Section 7.4 of the Receiving Inspection procedure (OP-009 Rev E), respectively.

There was a total of eight (8) opportunities for improvement observed during the audit summarized below. For additional details, see the internal quality audit checklist.

Opportunity for Improvement #1

In review of the last two management review meeting minutes (12/21/22 and 6/9/23), several opportunities for improvement were identified:

- a) It is not clear from reviewing the meeting minutes what time period is being evaluated. Document the evaluation period in the Management Review Meeting Minutes form (FM-0063 Rev A).
- b) Record official job title and department on the attendance sheet (job titles should align with the organization chart).
- c) Ensure all topics reviewed in management review have their own section in the meeting minutes form (e.g., Review of Quality Objectives).
- d) Only the supplier performance of Class I suppliers was reviewed in the management review. It is recommended to specify which suppliers are required to be reviewed for the supplier performance metric in QP-014, not just the management review slides.

[ISO 13485:2016 cl. 5.1(d), 5.6; 21 CFR 820.20 (c)]

Opportunity for Improvement #2

Clearly identify supplier statuses in the Supplier Qualification procedure (QP-005 Rev B). Consider adding a "conditional" status for suppliers that are undergoing supplier evaluation and may be used conditionally. Example: Erica Livingston performed internal audit from 5/11 – 5/12 but was not approved until 5/18.

[ISO 13485:2016 cl. 7.4.1; 21 CFR 820.50 (a)(3)]

Opportunity for Improvement #3

Several GDP issues were noted during review of the DHR:

- a) Item 7 in Work Order form not checked (Lot #SLQ-81000406231)
- b) Not all corrections are initialed and dated (Lot #SLQ-81000406231 and Lot#SLQ-81041201231).



DOCUMENT TITLE:
Internal Quality Audit Final Report

Revision:
A

DOCUMENT #:
FM3-QM.SLQ017

Effective Date:
25Sep2020

- c) "N/A" not applied per requirements outlined in Quality Record SOP QP-003 (Lot #SLQ-81000406231).
- d) Some BOM items do not indicate type – document or material (Lot #SLQ-81000406231 and Lot#SLQ-81041201231).

[ISO 13485:2016 cl. 8.3; 21 CFR 820.70]

Opportunity for Improvement #4

Re-execute the OQ and PQ (TP-HDX-0005 and TP-HDX-0006) with established CV and rinse test procedures and acceptance criteria.

[ISO 13485:2016 cl. 7.5.6; 21 CFR 820.70 (i)]

Opportunity for Improvement #5

Record equipment ID and calibration due date of Magnehelic gauge when recording daily monitoring values for positive pressure.

[ISO 13485:2016 cl. 6.3, 6.4; 21 CFR 820.70 (c), (f), (g)]

Opportunity for Improvement #6

It is unclear what part revision is being inspected. Include recording of part revision to receiving inspection form.

[ISO 13485:2016 cl. 7.4.3, 8.4; 21 CFR 820.50 (a)(2), 820.80 (b)]

Opportunity for Improvement #7

Ensure CAPA forms are completed with up-to-date, accurate data and activities. Ensure CAPA data captured in multiple sources re accurate.

[ISO 13485:2016 cl. 8.4, 8.5; 21 CFR 820.100 (a)(1)]

Opportunity for Improvement #8

Ensure CAPA documentation is completed in a timely, accurate manner. Ensure actions taken were documented, signed/initialed, and dated.


[ISO 13485:2016 cl. 8.2.5, 8.5.2, 8.5.3; 21 CFR 820.100 (a)(3), (a)(4), (a)(5), (b)]

CONCLUSIONS:

Based on the evidence observed, it is concluded that the management system is largely in conformity with the audit criteria and can be considered effective in assuring that the organization's objectives will be met and to ensure compliance to applicable regulatory and customer requirements. The four (4) findings of nonconformity and eight (8) observations are

	DOCUMENT TITLE: Internal Quality Audit Final Report	Revision: A
	DOCUMENT #: FM3-QM.SLQ017	Effective Date: 25Sep2020

	determined to be correctable and to not impact the overall determination of conformity of Pathway's QMS and customer product. A corrective action plan should be implemented in order to address the findings and observations before they become significant issues.
ADDITIONAL COMMENTS:	See attached audit checklist 23-01 for details of audit notes and observations.

Auditor Signature: 

Date: 28 Dec 2023