

ROCKLAND MARINE SERVICE

ENGINE DIAGNOSTIC INVOICE

Invoice #: RM-260219-17

Date: February 19, 2026

Customer: A. Croft

Vessel: EILEEN C

CUSTOMER CONCERN

Owner reported engine running warmer than usual on several trips late last season. Requested inspection before spring preparation work begins.

DIAGNOSTIC WORK PERFORMED

- Visual inspection of cooling system
- Checked raw-water intake and hoses
- Removed and inspected impeller housing
- Tested water flow at idle
- Engine warm-up and temperature monitoring

TECHNICIAN NOTES

Impeller showed signs of wear and was replaced. No blockage found in intake line. Water flow improved after replacement. Engine temperature remained within expected operating range during dock testing. Recommend monitoring temperature gauge during first weeks of fishing activity.

LABOR: \$142.50

PARTS: \$60.50

TOTAL DUE: \$203.00 (PAID)

Thank you for your business.