Kendall Toyota, Service Department

10943 S Dixie Hwy, Miami, FL 33156 | Invoice 463128

Date: December 13, 2025 | Customer: Michelle Brooks | Advisor: J. Fuentes

Vehicle: 2023 Toyota Highlander XLE | VIN: 5TDGZRBH8PS123847 | Mileage in: 29,847

Service Item	Amount
30,000 mile service, synthetic oil and filter	$89.95
Tire rotation and pressure set	$29.95
Cabin air filter, replaced	$49.95
Engine air filter, replaced	$39.95
Wiper blade set, replaced	$36.00
Multipoint and brake inspection	$0.00
Shop supplies	$14.50
Subtotal	$260.30
Sales tax, 7 percent	$18.22
Total	$278.52

Inspection notes: brakes at 7 mm front, 8 mm rear, tires at 6/32, battery tests good. No additional service recommended before the 40,000 mile interval.

Thank you for servicing with Kendall Toyota. Next recommended service at 40,000 miles.