Repair Estimate B (fictional garage)

Garage	Test Garage Beta Ltd (fictional)
Estimate date	2026-09-17
Vehicle	UBZ 482K

Item	Qty	Unit UGX	Line UGX
Front bumper replace	1	900,000	900,000
Bonnet panel repair and respray	1	1,250,000	1,250,000
Headlamp assembly LH	1	700,000	700,000
Labour	1	520,000	520,000
Paint materials	1	250,000	250,000
TOTAL			**3,770,000**