

Electrical Maintenance Record

Terminal: Kakkanad

Status: Medium

Detail: Minor flickering reported in dock lighting. Transformer 4B requires fuse replacement.