

**E Roz** <evanroz@gmail.com>

RE: Compliance

1 message

+WPG725 - CCA RTB <rtb@gov.mb.ca>Tue, Jan 16, 2024 at 12:38
PM

To: Evan Rosner <evanroz@gmail.com>

Good afternoon,

The tenant that has the issue with the window not opening should complete a Repair form and provide that to the Landlord as well as to the RTB office. A file in this office will then be opened. As well if the Property Management is not complying with fire related procedures you may wish to contact 311, City of Winnipeg, Bi-law Enforcement Unit. If this is not in the City of Winnipeg, you would contact the R.M. in your catchment.

Best regards,

Karen

Client Services Officer

RTB

From: Evan Rosner <evanroz@gmail.com>
Sent: Monday, January 15, 2024 8:55 AM
To: +WPG725 - CCA RTB <rtb@gov.mb.ca>
Subject: Compliance

Good morning,

I'm writing with concern about Thorwin Properties non-compliance with fire related procedure and protocol.

On January 14 around 7 pm the main building fire alarm was triggered. It continued until a tenant called 911 in order to alert the fire department who can only turn off the alarm at the building. The issue appears to be a failure in compliance in which the tenant responsible for the smoke produced by burning food was not informed about fire safety procedure and protocol. In addition, the reason for the main alarm system being triggered is due to the tenant being unable to open the windows in their suite and allow exit for the smoke.

The tenant in question is a family of newcomers and they should not be held responsible for their ignorance of procedure when language difficulties are a factor. Fire safety protocol documentation do not appear to be available through Thorwin Properties, and if they do exist, they were not communicated to the tenant in an effective manner, endangering the safety of the community and requiring me to take an active role in the protection of the community by organizing response.

An investigation is needed into the building's alarm system and its communication with authorities and signage and documentation necessary to inform tenants of protocol and procedure. My understanding is that the alarm does not communicate its triggering with the authorities and it is required that the tenants contact 911 in order to call the fire department and have the officers come to turn off the alarm.

The property manager, Grant Steele, arrived at the exact same time as the fire response team and did not check in with all building residents to confirm that there was no danger after the alarm was turned off.

It appears that Thorwin Properties does not have an effective plan or communication of plan for procedure and this constitutes a serious safety issue for the tenants of the building. It also appears that the windows are a safety issue and their functioning needs to be assessed.

Thank you,

Evan Rosner

10-585 Corydon Ave

R3L0P3

2048991499



Repair form.doc
114K