

A5

FUNCTION Indicator light A1 series				
AMBIENT TEMPERATURE	125 ℃			
GWT	850 °C			
GWT NO FLAME (<2sec)	650 °C			














DRAWING











A7

FUNCTION	Indicator light A4 series			
AMBIENT TEMPERATURE	125 °C			
GWT	850 °C			
GWT NO FLAME (<2sec)	650 °C			














DRAWING



TERMINAL















Z	١	′	X		
0,7 1,25	13,0	±0,1	19,0	±0,2	
1,25 2,0	13,0	±0,1	19,3	±0,2	
2,0 3,0	13,0	±0,1	19,6	±0,2	
	. 0,0		,.		





FUNCTION

RATING

BODY COLOR

LENS COLOR

2

200 - 250 VAC T125 °C VDE 710

200 - 250 VAC T65 °C UL 496 CSA C22.2

1 black

X ? custom

ILLUMINATED 🖟














Z	Y	,	X	X		
0,7 1,25	22,0	±0,1	19,0	±0,2		
1,25 2,0	22,0	±0,1	19,3	±0,2		
2,0 3,0	22,0	±0,1	19,6	±0,2		

		TERMINAL	FUNCTION	RATING	BODY COLOR	LENS COLOR					
A	7						0	0	0	0	0

FUNCTION

1

RATING

2 200 - 250 VAC T125 °C VDE 710

200 - 250 VAC T65 °C UL 496 CSA C22.2

BODY COLOR

1 black

X ? custom

ILLUMINATED 🖟

LENS COLOR









custom