
AI MECH LAB

Mechatronics Course — Beginner Stage




Module 2 · Topic 2.4

Reading Datasheets and Using a Multimeter

Reading Datasheets and Using a Multimeter

Every component you've met so far, resistors, capacitors, diodes and transistors, has a limit. Push a resistor past its power rating and it cooks. Feed a transistor more current than it can take and it dies, often silently, and you spend two hours debugging code that was never the problem. Two skills protect you from this: knowing what a component is rated for, and knowing what your circuit is actually doing. The first comes from the datasheet. The second comes from the multimeter.




When a circuit fails, check the hardware before you blame the code.

What a datasheet is

A datasheet is the manufacturer's official statement of what a component does and what it can survive. It is written by the people who built the part, so it settles any argument about how it behaves. Tutorials, forum posts and blog articles can be wrong. The datasheet is the primary source, and you find it by searching the part number followed by “datasheet”.


Datasheets look intimidating because they are dense, but nearly all of them follow the same structure, and you only need a few sections.



The six sections of a typical datasheet. Absolute Maximum Ratings (highlighted) is the one you must never skip.


The first page gives a one-paragraph description of the part, a feature list, and usually a pinout diagram. Read this first to confirm you have the right component for the job.

The pinout shows which pin is which. This matters more than it sounds. A transistor has three legs, and the same package can have its legs arranged differently across manufacturers. Wiring the collector where the emitter should go is one of the most common beginner mistakes, and the pinout prevents it. Note also that pinout diagrams are drawn from the top or bottom of the part, and the sheet says which.



The same transistor drawn from two viewpoints. The leg order flips between views, so always check which view the datasheet uses.


Absolute maximum ratings are the limits you must never exceed. For a typical small-signal NPN transistor, this table might list a maximum collector current of around 800 mA, a maximum collector-emitter voltage of around 40 V, and a maximum power dissipation of a few hundred milliwatts. These figures are illustrative, typical of this kind of part rather than taken from one specific datasheet. They are not operating targets. They are the edge of the cliff. A good habit is to design so you stay well under them, commonly at half or less of the maximum, to leave margin for heat, supply fluctuations and mistakes.



Design inside the safe zone, at about half the absolute maximum or less, not at the edge.

Electrical characteristics are the values the part actually delivers under stated test conditions. For a transistor, this includes its current gain, the voltage drop when it is fully switched on, and how quickly it switches. Read the conditions printed next to each value. A gain figure measured at 10 mA collector current may be very different at 500 mA. Beginners often quote a number from the table without noticing it was measured under conditions that don't match their circuit.

Typical, minimum and maximum columns. Many values appear in three columns. Typical is what you'll usually see. Minimum and maximum are the guaranteed bounds across manufacturing variation. When you are designing something that must work reliably, design against the worst case, not the typical one. If the gain is guaranteed to be at least 100 and typically 200, build the circuit so it works at 100.




Design for the guaranteed minimum, not the typical value.

Graphs and package drawings come last. The graphs show how behavior changes with temperature and current, which is useful once you start pushing a part. The package drawing gives physical dimensions, which matters when you design a PCB or a 3D-printed mount.

A practical way to read an unfamiliar datasheet: confirm the part type on page one, check the pinout, check the absolute maximum ratings against your circuit, then read the electrical characteristics for the specific values your design depends on. Everything else you can leave until you need it.

What a multimeter measures

A multimeter is the tool that tells you what is really happening in a circuit, as opposed to what you think is happening. It has two probes, a red one and a black one, and a dial that selects what you are measuring. The functions you will use constantly are these.




A handheld multimeter and its main dial positions. Note the separate mA jack, used only for current.

DC voltage. Set the dial to DC voltage (marked V with a straight line above a dashed line). Touch the black probe to the ground side and the red probe to the point you want to measure. Voltage is measured across two points, so the meter goes in parallel with whatever you are examining. This is the measurement you will take most often: Is the battery actually 3.7 V? Is the sensor receiving 5 V? Is the motor driver output reaching the motor?

Resistance. Set the dial to ohms (marked with the Greek letter omega). The meter sends a tiny current through the component and calculates resistance from the result. Two rules matter. First, power must be off, or the circuit's own voltage will give you a wrong reading and can damage the meter. Second, for an accurate reading, the component should ideally be out of the circuit, because other parts connected in parallel will skew the result.

Continuity. This setting, usually marked with a sound-wave or diode-like symbol, beeps when there is a low-resistance path between the probes. It is the fastest way to check whether a wire is broken, a solder joint is good, or two pins that should not be connected are accidentally shorted together. Like resistance, it should only be used with power off.

Current. Measuring current is where beginners get hurt. To measure current, the meter must become part of the circuit, in series, so the current flows through it. That means you break the circuit and insert the meter into the gap. Current measurement also uses a different input jack on most meters, often marked mA or A. If you leave the red probe in the current jack and then touch it across a voltage source, you create a near-short circuit through the meter, which blows its internal fuse at best. Make it a habit to return the red probe to the voltage jack immediately after any current measurement.




Voltage is measured across a component (parallel). Current is measured through the meter (series).

Diode test. This mode checks diodes and also LEDs and transistor junctions. A working silicon diode typically shows a forward voltage around 0.6 to 0.7 V in one direction and no reading in the other. This is a quick way to confirm a component is the right way round, or whether it has failed.

A worked example: putting both skills together

Suppose you want to switch a small DC motor from a microcontroller using a transistor. The datasheet for your transistor lists a maximum collector current of 800 mA. You measure the motor's running current with the meter in series and read 250 mA. That is comfortably under the limit, at roughly a third of it, so the transistor is a reasonable choice. You then measure the stall current, which means briefly holding the motor shaft still, and read 900 mA. Now you know the transistor would be overloaded if the motor ever jams. The datasheet told you the limit and the multimeter told you the real demand, and together they showed a problem before anything burned. The fix is to choose a transistor, or a motor driver, with a higher rating.



Running current is safe, but stall current exceeds the transistor's limit.

Safety habits worth building now

Turn the power off before measuring resistance or checking continuity. Start on a higher range if your meter is manual, and work down. Never measure current across a voltage source. Keep your fingers behind the probe guards. And never use a hobby-grade meter on mains electricity unless it is rated for it. Mains voltage can kill, and it is outside the scope of anything you will build in this course.

Where this leaves you

You now have the two habits that separate someone who guesses from someone who engineers: check the rating before you build, and measure the result after. That completes Module 2. You understand voltage, current and resistance, how series and parallel circuits behave, what the essential components do, and how to verify all of it on a real bench. Next comes Module 3, where we move from powering circuits to sensing the world with them, starting with the question of what a sensor actually is and how analog and digital signals differ.