

Technical Service Information

FORD TAURUS/SABLE AXODE (AX4S)

3.0L, 12 VALVE VULCAN ENGINE, REAR MAIN OIL SEAL LEAK

COMPLAINT: After flywheel replacement, Ford Taurus/Sable vehicles equipped with the 3.0L, 12 Valve

Vulcan engine, may return with an engine rear main oil seal leak. The vehicle did not have

this leak after the road test leak check.

CAUSE: The cause may be over tightening of the flywheel to crankshaft bolts, as the 3.0 Liter, 12

valve Vulcan engine can very easily have the crankshaft pulled out of round by over

tightening.

CORRECTION: When replacing the flywheel, be sure to install flywheel with the stiffener plate towards the

transmission and *torque* the flywheel to crankshaft bolts to 54-64 Ft. Lbs. in a cris-cross

pattern. Refer to Figure 1.

