

Technical Service Information

THM 200C WRONG GEAR STARTS / NO THIRD GEAR

COMPLAINT: Wrong gear starts / no third gear

CAUSE: One possible cause can be a broken 2-3 throttle valve Spring.

CORRECTION: Thoroughly clean the control valve assembly and install a new T.V. spring.

