

## **Technical Service Information**

## TOYOTA A140E EARLY STACKED SHIFTS

**COMPLAINT:** Early stacked shifts at moderate to heavy throttle only, and normal operation at light throttle.

The vehicle shifts properly with the cable disconnected.

**CAUSE:** Shifts solenoids may be partially restricted.

## **CORRECTION:** USE THE FOLLOWING TEST PROCEDURE:

1. Raise the wheels off the ground, and run the vehicle with the shift lever in 2nd C'2"), with the engine at 1200 RPM. Both shift solenoids will be energized (OPEN).

- 2. Then pull the cable all the way to maximum pressure.
- 3. If the transmission then shifts to 1st gear, the number 2 shift solenoid is restricted.
- 4. If the transmission then shifts to 2nd gear, the number 1 shift solenoid is restricted
- 5. If the transmission then shifts to 4th gear, both shift solenoids are restricted

NOTE: The number 1 solenoid wire is white, and the number 2 solenoid wire is black. Replace defective solenoid/solenoids.




Figure 1

Copyright © 2000 ATSG