

## **Technical Service Information**

## FORD E4OD BOOST VALVE AND SLEEVE NOW AVAILABLE

There is now available from Ford Motor Company, a pressure regulator boost valve and sleeve assembly for the E4OD transmissions. When servicing the E4OD transmission inspect the main regulator boost valve and sleeve assembly for any signs of wear, and replace as necessary with part number E9TZ-7D003-AA. Refer to Figure 1 for the location in oil pump cover, and to Figure 2 for proper assembly.




Figure 1



## **Technical Service Information**




Figure 2