

THM 440-T4 3RD CLUTCH LINING CHANGE (UPDATE)

CHANGE: Entirely new parking lock and actuator system.

REASON: To expand model usage that would include vehicles with a heavier Gross Vehicle Weight

(GVW).

PARTS AFFECTED:

- (1)TRANSAXLE CASE- Bore diameter for the actuator guide has been increased by .026", to accommodate the new actuator guide (See Figure 1).
- (2) ACTUATOR GUIDE Outside diameter has been increased by .026" for the increased diameter of the %.0let~~ on the parking rod. The plunger assembly and spring have been eliminated. The slot in the actuator guide has been eliminated (See Figure 2).
- (3) ACTUATOR GUIDE "0" RING The "0" ring is now larger diameter to seal larger diameter actuator guide (See Figure 2).
- (4) PARKING ACTUATOR ROD The "Bullet" on the park rod is now .070" larger in diameter, and the length increased by .543" (See Figure 3).
- (5) PARKING PAWL The parking paw1 lock-out pin has been eliminated, and the dimension (Width) of the parking paw1 was reduced by .039" (See Figure 4). NOTE: Parking paw1 is an integral part of final drive ring gear.

INTERCHANGEABILITY:

THE NEW PARK LOCK SYSTEM PARTS 'CANNOT'" BE USED M SERVICE PAST MODELS UNLESS ALL THE COMPONENTS ARE REPLACED, INCLUDING THE TRANSAXLE CASE.

SERVICE INFORMATION:

1990 Transaxle Case (All Bcept OLAH)	
1990 Transaxle Case (Model OLAH)	8668986
1990 Actuator Assembly (All)	8675325
1990 Park Rod Assembly (All)	
1990 Final Drive Ring Gear (All)	



SERVICE INFORMATION:

DESCRIPTION			MODELS	PART NO.
1989 Calibration	Update 1	Kit	9AAH, 9ABH, 9AFH	8675936
1989 Calibration	Update 1	Kit	9BAH, 9BDH	8675937
1989 Calibration	Update l	Kit	9BFH, 9BMH	8675938
1989 Calibration	Update 1	Kit	9внн	8675939
1989 Calibration	Update i	Kit	9ВЈН	8675940
1989 Calibration	Update I	Kit	9BPH	8675941
1989 Calibration	Update H	Kit	9BWH, 9VXH	8675942
1989 Calibration	Update i	Kit	9CDH, 9CLH, 9CZH	8675943
1989 Calibration	Update I	Kit	9PAH	8675945
1989 Calibration	Update I	Kit	9CPH, 9CYH	8675946
1989 Calibration	Update H	Kit	ОСНН	8675947
1989 Calibration	Update 1	Kit	ОСЈН	8675948
3rd Clutch Plate	Package	(New B	lack Stripe)	8662990
3rd Clutch Plate	Package	(Previ	ous Models)	8662954







Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP







OLD MODEL	NEW MODEL	CODES	CODE INFORMATION
AAH	ACH		
ABH	ADH		
AFH	AHH		(*) = NO CHANGES (NO NEW 3RD CLUTCH PLATES)
(HLA)	(AJH)	{*}	(O) = EARLY 1990 MODEL
(ANH)	(ANH)	(*)	(O) = EARLY 1990 WODEL
(ATH)	(ATH)	(*)	
(OLAH)	(OLAH)	(*) (0)	
(OLCH)	(OLCH)	(*)	
PAH	P8H		NOTE: IF THE MODEL CODES CHANGED THEN THE
VXH	VYH		3RD CLUTCH PLATE ASSEMBLY AND CALIBRATIONS
BAH	WBH		DID ALSO.
BDH	WCH		
ВЕН	WLH		
ВМН	WKH]	
внн	WRH		
BJH	WZH		
врн	WTH		
BWH	WUH		
CDH	YAH		
CLH	YBH		
СРН	YCH		
СҮН	YFH		
CZH	HLY		
оснн	OYKH	(0)	
осин	OYLH	(0)	



MODELS	VALVE BODY I.D.	MODELS	SPACER PLATE LAST FOUR NUMBERS
AJH	85-1	HLA	8394
ACH, ADH, AHH	9A-3	ACH, ADH, AHH	5213
ANH, ATH	98-2	ANH, ATH	8415
WBH, WCH	9D-2	WBH, WCH	5103
WLH, WKH	9E-3	WLH, WKH	5091
WRH	9G-3	WRH	5091
WZH, WUH	9H-3	WZH	5099
		WUH	5097
WTH	91-3	WTH	5091
YAH, YBH, YJH	9M-2	YAH, YBH, YJH	5089
YCH	9₽-2	YCH	5093
РВН	9U-2	PBH	5101
OYKH	0Y-1	OYKH	5201
OYLH	0W-1	OYLH	5203
OLAH	0Z·1	0LAH	8874
YFH	9C-0	YFH	8273

The last number of the valve body I.D. can be the same as indicated or higher. The higher number means that it was updated.

Figure 3







Figure 4








Figure 5 Figure 6




Figure 7