

Technical Service Information

THM 4L30-E VALVE BODY SCREENS


COMPLAINT: Previously, unavailable valve body screens required that a complete valve body be purchased

CAUSE: Parts personel were unable to find the part numbers for the screens.

CORRECTION: There are now part numbers available from Isuzu to service the valve body screens individually. Refer to Figure 1 for the location of the Force Motor Screen and Figure 2 for the

SERVICE INFORMATION:

Force Motor Screen (Isuzu part number)	. 8-96041-009-0
PWM Band Control Solenoid Screen (Isuzu part number)	. 8-96041-012-0





Technical Service Information




Figure 2