

Technical Service Information

FORD E4OD OVERDRIVE SECTION FAILURE

COMPLAINT: Overdrive planetary and overdrive sprag failure due to lack of lube.

CAUSE: The cause may be a plugged or restricted lube passage in pump cover. There is a ball and spring

under the orificed cup plug making this passage prone to clogging up.

CAUSE: Clean out the lube passage.

To check for restriciton blow into hole in pump cover. (See FIG #1) Air should exit from holes

in rear of stator shaft as shown in Figure #2.




Figure 1



Technical Service Information




Figure 2