

Technical Service Information

THM 440-T4 NEW DESIGN O.D. SHAFT WITHOUT BEARING

CHANGE: Beginning on June 1, 1993 (Julian Date 152) ALL THM 4T60-E transaxles were built with a

new design output shaft WITHOUT a caged needle bearing, a new 4th clutch hub and shaft, a

new input housing assembly, 'and a new input sun gear.

REASON: To eliminate a transaxle vibration at an engine speed between 3000-5000 RPM, when in 2nd

gear ONLY, and increase pleaseability concerns.

PARTS AFFECTED:

- (1) OUTPUT SHAFT Caged needle bearing located in the center of the output shaft has been eliminated, as shown in Figure 1.
- (2) INPUT/3RD CLUTCH HOUSING ASSEMBLY Caged needle bearing ADDED to the input housing assembly, and located on the inside diameter of the input shaft, as shown in Figure 2.
- (3) 4TH CLUTCH HUB AND SHAFT Hardened sleeve added to the shaft next to the splines that is 1.310" in diameter, and rides in the added bearing in the input/3rd clutch housing, as shown in Figure 2.
- (4) INPUT SUN GEAR Since the sun gear no longer rides on a bearing, it was not necessary to machine the surface finish on the inside diameter. The inside diameter has been reduced preventing it from being installed into transaxle with a bearing on the output shaft.

INTERCHANGEABILITY:

The parts listed above will back service ALL 4T60-E transaxles when used as a package, and will also service 4T60 (440-T4) transaxles back to 1989. The 4th clutch hub and shaft assembly will back service all 4T60 (440-T4) and 4T60-E transaxles, and id compatable with previous design level parts. The input sun gear inside diameter has been reduced preventing it from being installed in transaxle with a bearing on the output shaft. Previous input sun gear OEM part number 8682441 (For Dual Sprag) can be used in either application.

SERVICE INFORMATION:

4th Clutch Hub and Shaft Assembly (New Design	24201094
Output Shaft (New Design)	8683560
input/3rd Clutch Housing and Bearing Asm (New Design)	8651937
Input Sun Gear (New Design)	8683559
Vibration Repair Package	
(Includes 4 Parts Listed Above)	8651936



Technical Service Information




Figure 1



Technical Service Information




Figure 1