

Technical Service Information

CHRYSLER A500/518 L/R DRUM THRUST WASHER ELIMINATED

CHANGE:

During the 1989 model year, a running change was made to the Low/Reverse drum, that eliminated the thrust washer under the snap ring that holds the Low/Reverse drum on the overdrive piston retainer (See Figure 1).

REASON:

Improved assembly line process.

PARTS AFFECTED:


(1) LOW/REVERSE DRUM ASSEMBLY - The thrust washer recess in the center of the Low/Reverse Drum was eliminated, as shown in Figure 2.

(2) LOW/REVERSE DRUM THRUST WASHER - Eliminated.

INTERCHANGEABILITY:

The 1st design level and 2nd design level parts are interchangeable, as long as compatable parts are used together.

- (1) 1ST DESIGN LEVEL The Low/Reverse Drum WITH the thrust washer recess in the center of the drum REQUIRES the thrust washer between the snap ring and the Low/Reverse Drum (See Figure 2).
- (2) 2ND DESIGN LEVEL The Low/Reverse Drum WITHOUT the thrust washer recess (Flat Surface) in the center of the drum does not use the thrust washer. (See Figure 2).



AUTOMATIC TRANSMISSION SERVICE GROUP

94-32

Page 1 of 2



Technical Service Information




Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP