

Technical Service Information

FORD AOD-E/4R70W SLIPPING OR PROLONGED 1-2 UPSHIFT

COMPLAINT: Before and/or after rebuild, the vehicle exhibits a slipping condition on the 1-2 upshift, and

sometimes will not be displayed untill some miles have been put on the vehicle.

CAUSE: The cause may be, premature 1-2 accumulator seal wear, which also creates the case

accumulator bore to become scuffed, which leads to the loss in the 1-2 shift.

CORRECTION: Replace the cast aluminum 1-2 accumulator piston with a new design one piece stamped

steel piston with molded rubber lip seals, and replace the top accumulator spring with the revised parts available from Ford Motor Co. Case replacement should not be necessary with the use of the revised stamped steel accumulator piston. Refer to Figure 1 to remove the piston assembly. Refer to Figure 2 for illustration of both design stack-ups, and to Figure 3

for a chart to install the proper revised springs into the proper model.

SERVICE INFORMATION:

1-2 Accumulator Piston (New Design)	F7AZ-7F251-AA
1-2 Accumulator Spring, Bottom, (Purple)	F3LY-7F284-A
1-2 Accumulator Spring, Bottom, (Pink)	F4UZ-7F284-A
1-2 Accumulator Spring, Bottom, (Violet)	F7AZ-7F284-BA
1-2 Accumulator Spring, Top, (White)	F7AZ-7F284-AA
1-2 Accumulator Spring, Top, (Dk. Blue)	F7AZ-7F284-CA
1-2 Accumulator Spring, Top, (Lt. Blue)	F75Z-7F284-AA
1-2 Accumulator Spring, Top, (Brown)	F75Z-7F284-BA

Note: When referencing spring location, bottom refers to the bottom of the transmission as it sits in the vehicle (pan side).





Figure 1



Technical Service Information



Note: When referencing spring location, bottom refers to the bottom of transmission as it sits in the vehicle (pan side).



Technical Service Information

		1992	1993	1994	1995	1996	1997
Crown Victoria 4.6L	TOP	NONE	NONE	F7AZ-CA (Dk. Blue)	F7AZ-AA (White)	F7AZ-AA (White)	F7AZ-AA (White)
Grand Marquis 4.6L	BOTTOM	F7AZ-BA (Violet)	F7AZ-BA (Violet)	F7AZ-BA (Violet)	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)
Mark VIII 4.6L 4V	TOP	NA	F75Z-AA (Lt. Blue)	F75Z-AA (Lt. Blue)	F75Z-AA (Lt. Blue)	F75Z-AA (Lt. Blue)	F75Z-AA (Lt. Blue)
	BOTTOM	NA	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)	F4UZ-A (Pink)
Mustang 3.8L	TOP	AN	NA	NONE	NONE	F7AZ-AA (White)	F7AZ-AA (White)
	BOTTOM	AN	NA	F3LY-A (Purple)	F3LY-A (Purple)	F4UZ-A (Pink)	F4UZ-A (Pink)
Mustang 4.6L	TOP	AN	NA	NONE	NONE	F75Z-AA (Lt. Blue)	F75Z-AA (Lt. Blue)
	BOTTOM	AN	NA	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)
Mustang 5.0L	TOP BOTTOM	A N N	AN AN	NONE F3LY-A (Purple)	NONE F3LY-A (Purple)	N A A	NA NA
Thunderbird 3.8L &	TOP	NA	NA	NONE	NONE	F7AZ-AA (White)	F7AZ-AA (White)
Cougar 3.8L	BOTTOM	NA	NA	F3LY-A (Purple)	F3LY-A (Purple)	F4UZ-A (Pink)	F4UZ-A (Pink)
Thunderbird 4.6L &	TOP	NA	NA	NONE	NONE	F75Z-AA (Lt. Blue)	F752-AA (Lt. Blue)
Cougar 4.6L	BOTTOM	NA	NA	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)
Town Car 4.6L	TOP	NONE	NONE	F7AZ-CA (Dk. Blue)	F7AZ-AA (White)	F7AZ-AA (White)	F7AZ-AA (White)
	BOTTOM	F7AZ-BA (Violet)	F7AZ-BA (Violet)	F7AZ-BA (Violet)	F3LY-A (Purple)	F3LY-A (Purple)	F3LY-A (Purple)
Econoline	TOP	NA	NA	NA	NA	NA	F75Z-BA (Brown)
4.2L & 4.6L	BOTTOM	NA	NA	NA	NA	NA	F4UZ-A (Pink)
Econoline 5.0L	TOP	NA	NA	F7AZ-AA (White)	F7AZ-AA (White)	F7AZ-AA (White)	NA
	BOTTOM	NA	NA	F4UZ-A (Pink)	F4UZ-A (Pink)	F4UZ-A (Pink)	NA
Expedition 4.6L	TOP	NA	NA	NA	NA	NA	F752-AA (Lt. Blue)
	BOTTOM	NA	NA	NA	NA	NA	F4UZ-A (Pink)
Explorer 5.0L &	TOP	NA	NA	NA	NA	F7AZ-AA (White)	F7AZ-AA (White)
Mountaineer	BOTTOM	NA	NA	NA	NA	F4UZ-A (Pink)	F4UZ-A (Pink)
F-150 4.2L	TOP	NA	NA	NA	NA	F7AZ-AA (White)	F7AZ-AA (White)
	BOTTOM	NA	NA	NA	NA	F4UZ-A (Pink)	F4UZ-A (Pink)
F-150 4.6L	TOP	NA	NA	NA	NA	F75Z-AA (Lt. Blue)	F752-AA (Lt. Blue)
	BOTTOM	NA	NA	NA	NA	F4UZ-A (Pink)	F4UZ-A (Pink)
F-150 5.0L	TOP	NA	NA	F7AZ-AA (White)	F7AZ-AA (White)	F7AZ-AA (White)	NA
	BOTTOM	NA	NA	F4UZ-A (Pink)	F4UZ-A (Pink)	F4UZ-A (Pink)	NA
F-250 LD 4.6L	TOP	NA	NA	NA	NA	NA	F75Z-BA (Brown)
	BOTTOM	NA	NA	NA	NA	NA	F4UZ-A (Pink)
Notes: 1. The ba 2. When 3. "NA".	se part numb referencing s means that th	ver for the springs is -7F pring location, bottom i te AOD-E/4R70W trans	 The base part number for the springs is -7F284. For example, the part number for the pink spring is F4UZ-7F284-A. When referencing spring location, bottom refers to the bottom of the transmission as ir sits in the vehicle (pan side). "NA" means that the AOD-E/4R70W transmission was "Not Available", and not used for that model year. 	part number for the pini e transmission as ir sits : able'', and not used for t	t spring is F4UZ-7F284 in the vehicle (pan side). hat model year.		

97-64 Page 3 of 3