

Technical Service Information

THM 4L80-E NEW TEMP SENSOR

Some 1992 model THM 4L80-E/4L80-EHD transmissions are now equipped with a new Transmission Oil Temperature (TOT) sensor incorporated within the transmission wiring harness as shown in Figure 1, and replaces the TOT sensor that screwed into the valve body on previous models.




Figure 1

Copyright © 2001 ATSG