


Technical Service Information

THM 4L80-E NEW DESIGN TURBINE AND OUTPUT SHAFT SPEED SENSORS

There is now available from G.M. Service Parts, a 4th design Turbine and Output Shaft Speed Sensor for the THM 4L80-E/4L80-EHD transmissions, as shown in Figure 1. The previous OEM part number does not automatically supercede to the current part number. The new design level Speed Sensor is available under OEM part number 24203876, and two per transmission are required for all models except, 1994 and later 4FED models.

Always replace the Turbine and Output Shaft Speed Sensors with the newest design level part.



AUTOMATIC TRANSMISSION SERVICE GROUP

96-24 Page 1 of 1