

## **Technical Service Information**

## THM 440-T4 2ND CLUTCH LIP SEAL CHANGE

**CHANGE:** Revised 2nd Clutch Piston Inner Lip Seal.

**REASON:** (1) 2nd Clutch Inner Lip Seal - The new 2nd clutch inner lip seal is made from a different

material than the previous lip seal. The new seal is a "Viton" seal and can be easily identified

by its part number (8668074) moulded into the lip of the seal (See Figure 1).

## **INTERCHANGEABILITY:**

Will retro fit back to all previous models, and is highly recommended.

## **SERVICE INFORMATION:**

Contains:

(1) 2nd Clutch Inner Lip Seal (1) 2nd Clutch Outer Lip Seal




Figure 1