

Technical Service Information

THM 4L65-E NEW SUN SHELL AND THRUST BEARING

CHANGE:

Beginning at the start of production for model year 2001, General Motors introduced a new transmission designated THM 4L65-E (M32) with many engineering changes. Currently this unit is found in all 2001 Cadillac Escalade and any vehicle with 6.0L engine or larger, that was previously equipped with the THM 4L60-E transmision. One of the changes includes a new design sun gear shell and thrust bearing to replace the previous design washer, as shown in Figures 1 and 2.

REASON: Increased durability and reliability.

PARTS AFFECTED:

- (1) SUN GEAR SHELL The holes in the sun shell for the previous thrust washer have been eliminated, as shown in Figures 1 and 2, to accommodate the new thrust bearing.
- (2) REACTION CARRIER SHAFT Modified on the rear surface to accommodate the added thrust bearing, as shown in Figures 3 and 4.
- (3) THRUST BEARING Added for increased durability, as shown in Figures 3 and 4.

INTERCHANGEABILITY:

Will Not interchange with any previous design parts, but *Will* retro-fit back on any previous model 4L60-E transmission, *when used as a service package*.

SERVICE INFORMATION:


| Sun Gear Shell (New Design) | 24217145 |
|---------------------------------------|----------|
| Reaction Carrier Shaft (New Design) | |
| Sun Shell Thrust Bearing (New Design) | |

Copyright © 2001 ATSG

02-10 Page 1 of 3



Technical Service Information







Figure 1 Figure 2

02-10 Page 2 of 3



Technical Service Information






Figure 4