

Technical Service Information


FORD E4OD CHECK BALL CHANGE FOR 1990

There has been a change in checkball locations (CASE ONLY), for all 1990 model E4OD transmissions. Valve body locations remained the same as previous models.

REFER TO FIGURE 1 FOR BOTH YEARS, FOR THE VALVE BODY CHECKBALL LOCATION.

REFER TO FIGURE 2 FOR "1989" CHECKBALL LOCATIONS.

REFER TO FIGURE 3 FOR "1990" CHECKBALL LOCATIONS.





Technical Service Information




Figure 2



Technical Service Information




Figure 3