

Technical Service Information

THM 4T60-E NEW REVERSE REACTION DRUM FOR 1997 MODELS

CHANGE: Beginning at the start of Production for 1997 models, all THM 4T60-E transaxles were built

with a new design Reverse Reaction Drum, as shown in Figure

REASON: Greatly increased durability of the Reverse Reaction Drum.


PARTS AFFECTED:

(1) REVERSE REACTION DRUM - New design has been through a hardening process and can be identified by its blackened color, as shown in Figure 1.

INTERCHANGEABILITY:

The new design Reverse Reaction Drum will retro-fit back on all previous models of the THM 4T60-E transaxles.

SERVICE INFORMATION:



AUTOMATIC TRANSMISSION SERVICE GROUP