

Technical Service Information

CHRYSLER A604 REVISED LOW/REV PISTON SEALS

CHANGE: Beginning at the Start Of Production for 1995 model year all C

Beginning at the Start Of Production for 1995 model year, all Chrysler A604 (41TE) and A606 (42LE) transaxles were produced using revised seals for the Low/Reverse piston. The previous "Lip" type seals have been replaced by a "D" Ring type seal for both inner and outer

seals, as shown in Figure 1.

REASON: Improved durability and coast downshift quality.

PARTS AFFECTED:

(1) LOW/REVERSE PISTON SEALS - Both the inner and outer lip seals have been replaced by a "D" Ring type seal, as shown in Figure 1. There were no dimensional changes necessary to the Low/Reverse piston to accommodate the new "D" Ring seals. The seals are available under OEM part number 4659185 for the outer seal, and 4659184 for the inner seal.

INTERCHANGEABILITY:

The new "D" Ring type seals will back service ALL previous models of the Chrysler A604 (41TE) and A606 (42LE) transaxles, without any additional modifications or changes.

SERVICE INFORMATION:

Low/Reverse Piston Outer Seal ("D" Ring).	
Low/Reverse Piston Inner Seal ("D" Ring)	4659184



Technical Service Information

