

Technical Service Information

THM 4L60-E NEW DESIGN FILTER AND FILTER SEAL

CHANGE: Beginning in March, 1994, there was a molded 3-4 clutch piston that was implemented as a

running change into production.

REASON: Cost savings to produce.

PARTS AFFECTED:


3-4 CLUTCH PISTON - Now a stamped steel piston with both the inner and outer seals molded to the piston (See Figure 1).

INTERCHANGEABILITY:

The new molded 3-4.clutch piston will retro-fit back on all previous models, including the THM 4L60 (700-R4) back to 1982.

SERVICE INFORMATION:

MOLDED 3-4 CLUTCH PISTON



OEM PART #24200290

Copyright © 2000 ATSG