

FORD AX4S/AXOD-E CHANGES FOR THE CHAIN COVER AND NO. 1 AND NO. 3 THRUST WASHERS

CHANGE: Beginning on October 13, 1995, introduced as a running change for 1996 models, the AX4S

transaxles were built with new design Number 1 and Number 3 thrust washers (See Figure 1).

REASON: To improve the assembly process.

PARTS AFFECTED:

- (1) NUMBER 1 THRUST WASHER New design washer has symmetrically located tabs for ease of assembly, as opposed to the previous design with non-symmetrically located tabs. Refer to Figure 1 for illustrations of both designs.
- (2) NUMBER 3 THRUST WASHER New design washer is Black plastic with 3 symmetrically located tabs, as opposed to previous design bronze washer with tangs on the outside diameter. Refer to Figure 1 for illustrations of both designs.
- (3) CHAIN COVER New design will accept either the previous bronze No. 3 thrust washer with the tangs on outside diameter, or the new design Black plastic No. 3 thrust washer with the 3 symmetrically located tabs, as shown in Figure 3.

The previous design Chain Cover will accept n&y the bronze No. 3 thrust washer with the tangs on the outside diameter, as shown in Figure 2.

The new design Chain Cover will accept on the new design No. 1 thrust washer with 3 symmetrically located tabs, as shown in Figure 3.

The previous design Chain Cover will accept only the previous design No. 1 thrust washer with 3 non-symmetrically located tabs, as shown in Figure 2.


INTERCHANGEABILITY:

If replacement of the number 1 and/or the number 3 thrust washer becomes necessary, inspect the chain cover in the thrust washer tab areas to determine the correct thrust washers required. Refer to Figures 2 and 3.


SERVICE INFORMATION:

Number 1 Thrust Washer (Before 10/13/95)	E6DZ-7G099-A
Number 3 Thrust Washer (Before 10/13/95)	E6DZ-7G096-A
Number 1 Thrust Washer (On or After 10/13/95)	F5DZ-7G099-A
Number 3 Thrust Washer (On or After 10/13/95)	F5DZ-7G096-A







NUMBER 1 THRUST WASHER WITH NON-SYMETRICALLY LOCATED TABS PART NUMBER E6DZ-7G099-A



NUMBER 1 THRUST WASHER WITH SYMMETRICALLY LOCATED TABS PART NUMBER F5DZ-7G099-A



NUMBER 3 BRONZE THRUST WASHER WITH TANGS ON OUTSIDE DIAMETER PART NUMBER E6DZ-7G096-A



NUMBER 3 PLASTIC THRUST WASHER WITH SYMETRICALLY LOCATED TABS PART NUMBER F5DZ-7G096-A



NUMBER 3 THRUST WASHER

NUMBER 1 THRUST WASHER



REQUIRES THE BRONZE NO. 3 THRUST WASHER WITH TANGS ON THE OUTSIDE DIAMETER PART NUMBER E6DZ-7G096-A



REQUIRES THE PLASTIC NO. 1 THRUST WASHER WITH TABS THAT ARE NON-SYMETRICALLY LOCATED PART NUMBER E6DZ-7G099-A




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP



NUMBER 3 THRUST WASHER

NUMBER 1 THRUST WASHER



BRONZE WASHER E6DZ-7G096-A



BLACK PLASTIC F5DZ-7G099-A



REQUIRES THE PLASTIC NO. 1 THRUST WASHER WITH TABS THAT ARE SYMETRICALLY LOCATED PART NUMBER F5DZ-7G099-A




Figure 3
AUTOMATIC TRANSMISSION SERVICE GROUP