

Technical Service Information

FORD AODE NEW DESIGN PUMP BODY AND STATOR

CHANGE: Beginning at the start of production for 1995 model vehicles equipped with the AODE/4R70W transmission, a new design oil pump was implemented with re-routed and enlarged pressure cavities (See Figures 1 and 2).

REASON: Greatly improved oil pump efficiency for much improved durability.

PARTS AFFECTED:

- (1) OIL PUMP BODY Has an added pressure passage in pump body, shown in Figure 2, and is easily identified by casting number F5AP-7A105-AA located on the front side of pump body.
- (2) OIL PUMP STATOR Has a much enlarged pressure passage in pump stator as illustrated in Figure 2, and is easily identified by casting number F4AP-7A109 located on back side of the pump stator.

INTERCHANGEABILITY:

None of the parts listed above should be intermixed with one another. With the new design oil pump being so much more efficient than the previous design, it is *highly* recommended to use the new design pump assembly on *all* models of the AODE/4R70W transmission.


SERVICE INFORMATION:

Oil Pump Assembly (New Design) F4AZ-7A103-A

Copyright © 1998 ATSG



Technical Service Information





Technical Service Information

