

Technical Service Information

CHRYSLER A604 REVISED 2-4 CLUTCH PISTON RETAINER

CHANGE: Beginning at the Start Of Production for the 1995 model year, all Chrysler A604 (41TE) and

A606 (42LE) transaxles were produced using a revised 2-4 Clutch Piston Retainer with an

added lanced bleed orifice (See Figure 1).

REASON: Improved shift quality.

PARTS AFFECTED:

(1) 2-4 CLUTCH PISTON RETAINER - Lanced bleed orifice added to the retainer in the location shown in Figure 1.

The revised 2-4 Clutch Piston Retainer with the added lanced bleed orifice will back service ALL previous models of Chrysler A606 (41TE) and A606 (42LE) transaxles.

There was not a part number change, so the revised retainer is available under OEM part number 4431650.

