

## **Technical Service Information**

## NISSAN RL3F01A 1982-1983 STANZA/SENTRA FLARE ON 1-2 AND 2-3 SHIFTS

**COMPLAINT:** Engine flare on 1-2 and 2-3 shifts with the transmission in the drive range.

**CAUSE:** A broken back-up valve retaining plate.

**CORRECTION:** Install a new plate, part #31748-01X01




Figure 1