

Technical Service Information

CHRYSLER A604 "BUZZING" NOISE WHEN SELECTOR LEVER IS PLACED IN DRIVE OR REVERSE

COMPLAINT: When the manual selector lever is placed into either Drive and/or Reverse from the Park

and/or Neutral position, a "Buzzing" noise is heard coming from the transaxle area for

approximately one to two seconds and then stops.

CAUSE: This noise is created by the solenoid assembly which includes four different solenoids.

CORRECTION: The "Buzzing" noise described above is **NORMAL.** The **ONLY** thing that can be done to

help alleviate the "Buzzing" noise, is to ensure that the Solenoid Assembly Sound Cover is

present, and installed properly as shown in Figure 1.

