

SATURN NEW ACTUATORS FOR 2000

CHANGE: Beginning in the 2000 model year a 4th design Actuator was introduced to supercede all previous design Actuators. This change involves a complete redesign of the Actuator at the screened end.

REASON: Reduces the possibility for debris to stick a control actuator valve.

PARTS AFFECTED:

(1) ACTUATORS - 4th Design now has redesigned screens added to the control pressure side of the actuators as illustrated in Figure 1, and have the same resistance values as the 2nd and 3rd Design actuators, and are identified *without* the previous design plastic top or is called the Black Top Actuator. The 1st and 2nd Design actuators are shown in Figure 2. The 3rd and 4th Design actuators are shown in Figure 3. Actuator locations on the valve body are shown in Figure 4.

INTERCHANGEABILITY:

The 4th Design Actuator is the *only* Actuator that is available and will retrofit to previous models.

SERVICE INFORMATION:

4TH DESIGN ACTUATOR......21003344

Ath DESIGN ACTUATOR New design plastic cap and screens Copyright © 2005 ATSG

Figure 1

07-21

Page 1 of 4




1ST DESIGN CONTROL ACTUATOR SOLENOIDS 1991-1992

No longer available

Black or Blue Plastic Tops For Identification



Measures 2.5 to 4.5 Ohms Resistance




2ND DESIGN CONTROL ACTUATOR SOLENOIDS 1993-1996

No longer available

Red Plastic Tops For Identification



Measures 4.0 to 6.0 Ohms Resistance



Copyright © 2006 ATSG Copyright © 2005 ATSG




3RD DESIGN CONTROL ACTUATOR SOLENOIDS 1997-1999

No longer available

White Plastic Tops For Identification




Measures 4.0 to 6.0 Ohms Resistance




4th DESIGN CONTROL ACTUATOR SOLENOIDS ALL MODELS

No Color or Black Top




Measures 4.0 to 6.0 Ohms Resistance



Copyright © 2006 ATSG Copyright © 2005 ATSG



SATURN VALVE BODY ACTUATOR LOCATIONS



Copyright © 2006 ATSG Copyright © 2005 ATSG