


# **Technical Service Information**

### FORD AXOD-E PUMP CHECK BALL CHANGES


- 1. EARLY 1991 ONLY: USES 5 CHECKBALLS IN THE LOCATIONS SHOWN IN FIGURE 1.
- 2. LATE 1991 ONLY: THE B12 CHECKBALL THAT SEPARATED TV/L234 WAS ELIMINATED, AS SHOWN IN FIGURE 2. THIS REQUIRED A SPACER PLATE CHANGE.
- 3. 1992 MODEL ONLY: THE B13 CHECKBALL WAS ELIMINATED, ALLOWING FORWARD CLUTCH OIL TO EXHAUST UNORIFICED IN OVERDRIVE.
  THE B2 CHECKBALL WAS ADDED FORCING FORWARD CLUTCH OIL THRU
  THE "K" ORIFICE. REFER TO FIGURE 3.





## **Technical Service Information**

CHECKBALL LOCATIONS






### **Technical Service Information**

#### **CHECKBALL LOCATIONS 1992 ONLY**

**B13 CHECKBALL ELIMINATED** ALLOWING FORWARD CLUTCH OIL TO EXHAUST UN-ORIFICED IN O.D.



**B-2 CHECKBALL ADDED** FORCING FORWARD CLUTCH OIL THRU THE "K" ORIFICE